

Pre-Delivery Inspection (PDI) Form

	st below any dam. 1. Also note any " 2 and Sale (APS).	aged, incomplete, or missing items and anything that is not in good operations of items referred to in, or to be selected under, the Agreement
	and Bale (AFS).	PAGE #: OF
tem#	Room/Location	Description
0	MSTR ENS	REDUIRE SHOWER GLASS DOBR -METROPOLITAN X
2	KITCHEN	COUNTER TO RIGHT SE FRIDGE, CHIPS ON BACKSPLASH & RIGHT FRIDGE GABLE X
		TO HEW IMME
3)	MAINBATH	REWIRE MIRROR -METROPOLITIAN X
4	BSMT	COMPLETE RUN TO FOYER -NATIONAL V 96
5	BANT	FIXED GLASS TO RIGHT OF FLECTRICAL. PANIEL HAS STRESS CRACK- NEWWAR Y
6	EXTERIOR	CONPLETE PORCH ELECTRICAL - MYKON / 300
(1)	EXTERIOR	INSTAU GARAGE DOORS - ABBEY / JO
8	EXTERIOR	COMPLETE CAULKINGJ) / Att
9	EXTERIOR	PARGE BUNDATION @ RIGHT SIDE RETURN /
		5 INTERIOR
		4 EXTERISE
		4
		domeowner Signature.
		The Homeowner acknowledges and accepts
		that all initialed work has been completed in a workman like manner to their satisfaction.

WHITE COPY - Zancor Homes

Purchąser's signature

CANARY COPY - Purchaser

PINK COPY - Site



The items listed below were released to the homeowner(s) of

Lot # 9	Site/Phase:	Shoreline Point_	
√ House and Garage Door Keys	s		
√ Homeowner Manual (given at	PDI)		
N/A Recycling and Green Bins			
N/A Other			
The above items were received on this		May.	2023
Purchaser			
ruiciaser		Purchaser	