Enrollment:

Purchaser Name: Anshul Jain

Vishwanath Ramagundam

Phone Res:

Phone Bus: (647) 671-4275
Closing Date: June 15, 2023
Inspector: Gisella Fiore

ZANCOR HOMES PDI

Page 1 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 38B / 1B

Plan: Address: Municiaplity:

Inspection Date: May 29, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH			
MIRROR	MIRRORS THROUGHOUT NOT INSTALLED	 -	
FAUCETS/PLUMBING	UPGRADED BATH ACCESSORIES NOT INSTALLED THROUGHOUT	 -	
DINING ROOM			
WALLS	DENT IN STIPPLE CEILING RIGHT OF LIGHT FIXTURE	 	
KITCHEN			
CABINETS	CHIP ON BOTTOM GABLE BELOW SINK AT ISLAND	 	
	CHIP ON LEFT GABLE BESIDE GARAGE DOOR	 	
NOTE:	SCRATCH ON STEP TO GARAGE, VARNISH REQUIRED	 	
COUNTERTOPS	INSPECT EDGE OF COUNTERTOP FACING BREAKFAST AREA FOR CHIP	 	
MASTER BEDROOM			
FLOORING	ADJUST CARPET SHIM AT ENTRANCE TO ENSUITE THROUGHOUT UPPER FLOOR	 	
FOYER/HALL			
FLOORING	CHIP AT 2ND HARDWOOD PLANK AT ENTRANCE TO BEDROOM 2 IN UPPER ALL AND FILL NAIL HOLES BY NOSING	 	
STAIRS	DENT ON 7TH TREAD BELOW NOISING AT FIRST LANDING TO 2ND FLOOR	 	
SHARED ENSUITE			
VANITY CABINETS	CHIP ON RIGHT DOOR BELOW RIGHT SINK		
NOTE:	SETTLEMENT CRACK ON OPERATING WINDOW INSIDE SHARED BATHROOM	 	
UPPER HALL			
FLOORING	FLOOR SQUEAK AT 7 HARDWOOD PLANK FROM BEDROOM TWO	 	
BEDROOM 4 ENSUITE			
COUNTERTOPS	CHIP ON LEFT SIDE SPLASH	 	
POWDER ROOM			
SINK/FAUCET/PLUMBING	SINK STOPPER NOT HOLDING WATER	 = -	

Enrollment:

Purchaser Name: Anshul Jain

Vishwanath Ramagundam

Phone Res:

Phone Bus: (647) 671-4275
Closing Date: June 15, 2023
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 38B / 1B

Plan: Address: Municiaplity:

Inspection Date: May 29, 2023

LIVING ROOM			
FLOORING	CHIP ON 13TH HARDWOOD PLANK FROM LEFT WALL		
EXTERIOR			
NOTE:	EXTERIOR PLUG NOT INSTALLED AT REAR PATIO DOOR		

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Anshul Jain Vishwanath Ramagundam Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Gisella Fiore Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature 2023/05/29 May 29, 2023 Date (YYYY/MM/DD)