Enrollment:

Purchaser Name: Saurabh Jain

Phone Res:

Phone Bus: (647) 462-0444 Closing Date: June 26, 2023

Inspector: Alexandria Damianidis

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 24B / 1B

Plan: Address: Municiaplity:

Inspection Date: May 29, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

EXTERIOR		
NOTE:	ADJUST LENTIL AT HARDY BOARD LEFT OF WINDOW LEFT OF FRONT PORCH	
	CAULKING CRACKED LEFT WINDOW	
	REMOVE METAL FROM FRONT PORCH FOUNDATION WALL	
PORCH	PORCH CHIPPED	
	REMOVE MORTAR SPLATTERS AT FRONT PORCH	
PAINT	PAINT MISSING ON FRONT DOOR	
KITCHEN		
CABINETS	CHIP ON LEFT UPPER SHELF BESIDE FIREPLACE	
	CHIP AT CORNER CABINET BACK GABLE	
	CHIPS AT ISLAND GABLE FACING PATIO DOOR	
WINDOWS	CHIPS AT PATIO DOOR	
MASTER ENSUITE BATH		
VANITY CABINETS	CHIPS ON BOTTOM GABLE BELOW LEFT SINK BIG CHIP ON LEFT AND RIGHT GABLE BELOW	
	LEFT SINK SAME WITH RIGHT SINK LEFT DOOR LEFT DOOR	
MAIN BATHROOM		
VANITY CABINETS	SCRATCHES ON KICKPLATE	
UPPER HALL		
FLOORING	FLOOR SQUEAK IN UPPER HALL INFRONT OF BEDROOM 2	

Enrollment:

Phone Res:

Purchaser Name: Saurabh Jain

Phone Bus: (647) 462-0444

Inspector: Alexandria Damianidis

Closing Date: June 26, 2023

ZANCOR HOMES PDI Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 24B / 1B

Plan:

Address: Municiaplity:

Page 2 of 2 Inspection Date: May 29, 2023

FOYER/HALL		
STAIRS	CRACK ON 1ST SPINDAL AT FIRST LANDING	
	CHIP ON 6TH SPINDAL FROM MAIN TO FIRST LANDING	
	CHIP BELOW NOSING AT STAIRS FROM MAIN TO 1ST LANDING	
	VARNISH MISSING ON RAILING AT FIRST LANDING FROM MAIN	
	DAMAGED 8TH SPINDAL ON 2ND FLOOR	
	VARNISH REQUIRED ON 3RD TREAD AT MAIN FLOOR	
	HOMEOWNER REQUESTING 2ND COAT OF VARNISH THROUGHOUT, SOME SEE THROUGH PARTS IN STAIRS	
	CHIP ON NOISING AT FIRST LANDING	
POWDER ROOM	OHII ON NOISING ATTIHOT EANDING	
POWDER ROOM		
SINK/FAUCET/PLUMBING	WASTER STOPPER NOT HOLDING WATER DENTED DENTED DENTED	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Saurabh Jain

Purchaser's Name (print) Purchaser's Signature

Purchaser's Name (print) Purchaser's Signature

Alexandria Damianidis

Designate's Name (print) Designate's Signature

Inspector's Name (print) Inspector's Signature

Date (YYYY/MM/DD) 2023/05/29 May 29, 2023