

ATTORNEY Zircon Homes (Caledonia) Ltd Work Order
 Warranty Services
 Phone: (905) 738-7010
 Fax: (905) 738-5948

Closing Date: 09 Jun 22

Address: Caledon Club - Phase: 1 - Lot: 110A
Location: 06 Oct 22
Today's Date: Ramneek Kaur Bawa - Home: (847) 228-7313 - (raggi_ua@yahoo.com)
Contact(s): Jagdeep Singh Bawa - Home: (416) 454-4570 - (jaggi_ua@yahoo.com)
Email: jaggi_ua@yahoo.com

Company: Hewmar
Attention: Alex
Telephone: (905) 672-1233
Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
150805	PDI	LIVING ROOM-WINDOWS-ADJUST WINDOW RIGHT OF FIREPLACE		Need Frame
150806	PDI	BEDROOM #4-WINDOWS-ADJUST WINDOW CANNOT CLOSE		Complete
150818	PDI	FOYER/HALL-FRONT DOORS-ADJUST FRONT DOOR AND MAN DOOR		Complete

Date Completed:

Homeowner Signature: 
 The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: May 02/23

Trade Star Services Tech



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W169405
Pack Slip: 211032
Service Date: May 02, 2023

Priority: Normal

BUILDER

Customer: N000531

Name: ZANCOR CALEDON CLUB

Service Fax:

Site Fax:

Status:

SCHEDULED

RELEASED

City: CALEDON

Received: Oct 12, 2022

Service Phone(s):

Time: 1ST CALL

Site Phone:

Order: D380116-1

Lot#: 110A

Phase:

RESIDENT INFORMATION

Home Owner Name:

Address:

Home Phone(s):

Work Phone(s):

Cell Phone(s): 647-228-7313

Email(s): jaggi_ua@yahoo.com

LINKED ORDER INFORMATION (D380116-1)

Customer: N000531 ZANCOR CALEDON CLUB

Lot #: 110A

Model: 30-03 GREYSTONE (OPT. 4BED) (BK)

Phase:

SERVICE INSTRUCTIONS

ADJUST LIVING WINDOW (RIGHT OF FIREPLACE), BED4, FRONT DOOR AND G/H DOOR
OKAY JUST GIVE ME A CALL BEFORE COMING.

THANKS

JAGDEEP

4164544570 TENANT 289-654-2469

ADD:

LIVING ROOM FRAME TO BE REPLACED

PARTS REQUIRED

LN Item Description

72 NEWMAR VINYL CASEMENT

Location

RR/ G.ROOM

Specification

Size 24 X 68

Options

LEFT BK 61316 FJ

Qty

1

Problem Description:

Backup Signed by tenant

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Builder to re-check frame top & bottom

Solution:



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W169405
Pack Slip: 211032
Service Date: Feb 13, 2023

Priority: Normal

Status: **SCHEDULED**

BUILDER

Customer: N000531

City: CALEDON

Received: Oct 12, 2022

Name: ZANCOR CALEDON CLUB

Service Phone(s):

Time: PM

Service Fax:

Site Phone:

Order: D380116-1

Site Fax:

Lot#:

110A

Phase:

RESIDENT INFORMATION

Home Owner Name:

Address:

Home Phone(s):

Work Phone(s):

Cell Phone(s): 647-228-7313

Email(s): jaggl_ua@yahoo.com

LINKED ORDER INFORMATION (D380116-1)

Customer: N000531 ZANCOR CALEDON CLUB

Lot #: 110A

Model: 30-03 GREYSTONE (OPT. 4BED) (BK)

Phase:

SERVICE INSTRUCTIONS

ADJUST LIVING WINDOW (RIGHT OF FIREPLACE), BED4, FRONT DOOR AND G/H DOOR
OKAY JUST GIVE ME A CALL BEFORE COMING.

THANKS

JAGDEEP

4164544570 TENANT 289-654-2469

ADD:

LIVING ROOM FRAME TO BE REPLACED ✓ --- M/R

Problem Description:

Tenant did not sign Receipt

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$

Labour \$

Labour \$

P.O.#:

Cause:

Solution:

Living Room - 24x68 HL Black Frame only

Date Completed:

Feb 13/23

Approved: