



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W175866
Pack Slip: 215754
Service Date: Apr 03, 2023

Priority: Normal

BUILDER

Customer: N000508

Name: ZANCOR WHITEBY

Service Fax:

Site Fax:

Status:

SCHEDULED

City: WHITEBY

Service Phone(s):

Site Phone:

Lot#:

Received: Jan 11, 2023

Time:

Order: D374339-1

Phase: PH1

RESIDENT INFORMATION

Home Owner Name: KWADWO BOAKYE-YIADOM

Home Phone(s):

Cell Phone(s):

Address:

Work Phone(s):

Email(s):

bqwindows@gmail.com,
mameyaa2002@hotmail.com

LINKED ORDER INFORMATION (D374339-1)

Customer: N000508 ZANCOR WHITEBY

Model: TH-1

Lot #: BLK 7 - 41

Phase: PH1

SERVICE INSTRUCTIONS

FOYER/HALL - FRONT DOORS-ADJUST FRONT DOOR

Problem Description:

No Bunching Backing to Sign

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

April 03/23

Approved: *X*

Time:

Service Signature:

STEVE



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W175866
Pack Slip:215754
Service Date: Apr 03, 2023

Priority: Normal

BUILDER

Customer: N000508

Name: ZANCOR WHITBY

Service Fax:

Site Fax:

Status:

SCHEDULED

City: WHITBY

Service Phone(s):

Site Phone:

Lot#:

Received: Jan 11, 2023

Time:

Order: D374339-1

Phase: PH1

BLK 7 - 41

RESIDENT INFORMATION

Home Owner Name: KWADWO BOAKYE-YIADOM

Home Phone(s):

Cell Phone(s):

Address:

Work Phone(s):

Email(s): bqwindows@gmail.com,
mameyaa2002@hotmail.com

LINKED ORDER INFORMATION (D374339-1)

Customer: N000508 ZANCOR WHITBY

Model: TH-1

Lot #: BLK 7 - 41

Phase: PH1

SERVICE INSTRUCTIONS

FOYER/HALL- FRONT DOORS-ADJUST FRONT DOOR

Problem Description:

☐ Warranty

Material \$

Labour \$

Cause:

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

STEVE