

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W186756 Pack Slip:224825

Service Date: May 30, 2023

Priority:	Normal			Status: S		SCHEDULED					
BUILDER											
Customer:	N000633			City:	W	WASAGA BEACH			Received:	May 17, 2	2023
Name:	ZANCOF	R WASAGA SINGLES		Service Phon	e(s):				Time:	10AM - 2	PM
Service Fax:				Site Phone:					Order:	D385919	-1
Site Fax:				Lot#:	16	8			Phase:		
RESIDENT I	NFORM	ATION									
Home Owner I	Name: \	VADZIM KHARLANAU		Add	lress:	32	22 RAME	BLEWC	OOD DRIVE		
Home Phone(s	s): 4	116-807-8308		Wor	k Phone(	s):					
Cell Phone(s):	: 4	116-837-1867		Ema	ail(s):			_	gmail.com, @gmail.com		
LINKED ORI	DER INF	ORMATION (D3859	19-1)								
Customer: N	N000633	ZANCOR WASAGA S	INGLES			Lot #:	168				
Model: 6	60-01 (BLK)/LOT 168			Phase:							
SERVICE IN	STRUCT	TIONS									
KITCHEN PAT	TIO DOOF	R MOSQUITO NET O	N THE DOOR	R IS DAMAGE	ED						
PARTS REQ	UIRED										
LN Item Descr	•		Location	Specification	S	ize		Options	3		Qty
41 BUCKING	GHAM PL	JRCH. PATIO DOOR	BRK	SCREENS-I CEMENT-D		7.375 ×	(78.375	BUCK	316 RIGHT INGHAM PU DOOR	RCH.	1
Problem Desci	ription:					0,0					
Warranty		- W.W.		П	CHARGE	ABLES					
_ Material \$		_		Mat	erial\$	- 6 ***					
_abour \$				Lab	our\$	NI					
				P.O	.#:						
Cause:		21 0		1					1		
	Ke	Haral (	PATIO	2 /2	10	6 60	De v	4	Jon		
Solution:			100.00			200		'	2000		
Date Comple	eted: M	30-202	3	-	Approved	d: <b>4</b>		02)	· ·		
Т	Гіте:			Service	Signature	e:		ZA	HER		



Normal

Priority:

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076

SCHEDULED

Status:

F ( WO # W176142
Pack Slip:227757

Service Date: Apr 21, 2023

RELEASED

BUILDER										
Customer: N000750		City:	BRAMPTON	Received:	Jan 16, 2023					
Name: PARADISE HIGH POINT		Service Phone(s):		Time:	AM					
Service Fax;		Site Phone:		Order:	D386977-1					
Site Fax:		Lot#:	B306-5	Phase:						
RESIDENT INFORMATION					1					
Home Owner Name: N/A		Address:	N/A 1	56 Adven	Tura Rd					
Home Phone(s):		Work Pho	ne(s):	10 MB VCII	· I O					
Cell Phone(s):		Email(s):								
LINKED ORDER INFORMATION (D3	86977-1)									
Customer: N000750 PARADISE HIGH	POINT		Lot #: B3	06-5						
Model; 20C (DW)			Phase:							
SERVICE INSTRUCTIONS										
****KEY WITH SITE SUPERVISOR ****										
BROKEN GLASS PATIO DOOR OP										
ADD: BROKEN FRONT DOOR- BOTH										
PARTS REQUIRED	ine.	dunding	1. 94 10011	-1						
LN Item Description	Location	Specification Size Options Qty								
71 5' 4" CLAD DOOR SYS	FRT/ ENT	SLABS (ALL)	The second secon	OKIGHT STEEL 600	·=					
22 X 36		our bo (rice)	00.07.01.70	TYPE3 DW						
121 NEWMAR PATIO DOOR	GRT	SASH AND GLASS	35.6875 X 78.625	RIGHT DW CLR LO 3T/19/3T	OWE_ARG 1					
			MYOUN							
Problem Description:			U							
Warranty		CHAR	GEABLES							
Material \$		Material \$								
abour \$ Labour \$										
		P.O.#:		1						
Cause: Replacal	Rott	1 doc	Slabe	Sone						
Solution:	ria de	1000.6	101. PI	1 Ph- 11 C-						
TICES 14	10 00	01 01 00	42M-N-E	+ tans	MAIGMA					
Date Completed:	*	Appro	wed:							
Time:		Service Signature:								
				ZAHER						



## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP



WO # W178071 Pack Slip:223716 Service Date: Mar 02, 2023

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076

iie aktiibit								
Priority:	Normal		Status:		SCHE	DULED		
BUILDER								
Customer:	N000750		City:	City:		PTON	Received:	Feb 09, 2023
Name:	PARAI	DISE HIGH POINT	Service	Service Phone(s):			Time:	AM
Service Fax:			Site Phone:				Order:	D385639-1
Site Fax:			Lot#;		75		Phase:	
RESIDENT	INFOR	WATION						
Home Owner	Name:	PATEL, YASH SANJAYKUMAR		Address:		20 STELLART	ON CRESCENT	Г
Home Phone(	Home Phone(s): 647-575-3865, 647-469-9274			Work Ph		647-648-6020		
Cell Phone(s)	1			Email(s): yash631@g		yash631@gma	il.com	
LINKED OR	DER IN	IFORMATION (D385639-1)						
Customer; I	N00075	PARADISE HIGH POINT			Lot	#: 75		
Model:	45I (SB)	/RR.UPG			Pha	ise;		
SERVICE IN	STRUC	CTIONS						
EXTERIOR D	OOR AD	JUSTMENT: FRENCH DOOR NO	T PLUMB	VERY DE	RAFTY.	TO BE PROPER	LY ADJUSTED	
		ROOM AREA: INTERIOR		,				
SIDE DOOR N	NEEDS	TO BE ADJUSTED, VERY DRAFT OOR AREA: INTERIOR	Y LARGE	GAPS BE	TWEEN	DOOR AND JAN	MBS	
		DJUST VERY DRAFTY AREA: INTERIOR				ر.) سر	a na Dro	and the control
Problem Desc	ription;	not Home-	Hor	neon	ne1	Sall	( CIPI	F/
Warranty		1> +OF MAR	ch 6	II CHAR	GEABL	=9		-
Material \$				Material S		_0		
Labour \$				Labour \$				
				P.O.#;	***			
Cause:				1 .0,,,,				
Solution:								
Date Comple	eted:	3/2/23.		Appr	oved:	20.2	12 2	/.

Service Signature:

Supplier:
Newmar Window Manufacturing
7630 Airport Road
Mississauga, ON L4T 4G6

Work At: High Point Patel, Yash Sanjaykumar 20 Stellarion Crescent Brampton, ON LTA 5A6

Contact:
Patel, Yash Sanjayk
Umar
Home Ph: (647)575-3865
Bus. Ph:
Cell. Ph: (647)648-6020

yash631@gmail.com

Work Order: HPOINT, 00001836

Project: High

High Point 0075

Model: 45| 1
Builder:

Warranty Rep:

WO Type: Work Status:

Warranty Eff. Date: Order Date: Pre-Delivery Orientation In Process

02/08/2023

Priority: Low Priority

Last Scheduled Date: Date Expected: Completion Date:

Lot General Instructions

Work Order Instructions

Iten No.	n Description	item Status	Gause/ Resolution	Scheduled Date	Scheduled Time	Completion Date	
0004	properly adjusted Location: Great Room Area: Interior  Item Details  WINDOW Windows—Exterior Door Adjustment; french door not plumb, very drafty, to be properly adjusted  side door needs to be adjusted, very drafty large gaps between door and jambs Location; Main Floor Area: Interior	In Process		02/06/2023	11:45 AM		17
0006	Item Details  WINDOW Windowsskile door needs to be adjusted, very drafty large gaps between door and Jambs  missing window	In Process		02/06/2023	11:47 AM		
	Location: Basement Area: Interior  Item Details  WINDOW Windows—missing window	In Process		02/06/2023	11:59 AM		
0012	front doors to adjust very drafty Location: Foyer Area: Interior  Item Details						

Supplier: Newmer Window Manufacturing 7630 Airport Road Mississauga, ON L4T 4G6

Work At: High Point Patel, Yash Sanjaykumar 20 Stellarton Creacent Brampton, ON L7A 5A6

Contact: Patel, Yash Sanjayk

umar

Home Ph: (647)575-3865

Bus, Phi

(647)648-6020 Cell, Ph:

Work Order: HPOINT, 00001836

Project:

High Point

0075 Lot: 451.1 Model:

Bullder:

Work Status: Warranty Eff. Date:

WO Type:

In Process

Order Date:

Pre-Delivery Orientation

02/08/2023

02/03/2023

Priority:

Low Priority

Last Scheduled Date: Date Expected: Completion Date:

Item

No. Description

ltern Status Cause/ Resolution Scheduled

Scheduled Time

Completion

WINDOW Windows--front doors to adjust very drafty

In Process

02/06/2023

Date

12:07 PM

Vendor Signature:

nomeowner Signature.

Original