

## **NEWMAR WINDOW MFG. INC.** ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076

WO # W162404 Pack Slip:206644 Service Date: Jun 05, 2023

| Priority:                                      | Normal  |                                       | Status:                               | SCHEDULED                                      |               |              |  |
|--|---|---------------------------------------|---------------------------------------|--|---------------|--------------|--|
| BUILDER  |   |                                       |                                       |  |               |              |  |
| Customer:                                      | N000508   |                                       | City:                                 | WHITBY   | Received:     | Jun 24, 2022 |  |
| Name:  | ZANCOR WHITBY                                       |                                       | Service Phone(s):                     |  | Time:         |              |  |
| Service Fax:                                   |   | Site Phone:                           |                                       | Order:   | D374305-1     |              |  |
| Site Fax:                                      |   |                                       | Lot#:                                 | BLK 1-3  | Phase:        | PH1          |  |
| RESIDENT I                                     | INFORMATION   |                                       |                                       |  |               |              |  |
| Home Owner                                     | Name:   |                                       | Address:                              | 6727   |               |              |  |
| Home Phone(s):                                 |   |                                       | Work Phone(s):                        |  |               |              |  |
| Cell Phone(s):                                 |   |                                       | Email(s): chriswilson1984@outlook.com |  |               |              |  |
| LINKED OR                                      | DER INFORMATION (D374                               | 305-1)                                |                                       |  | <del>_</del>  |              |  |
| Customer:                                      | N000508 ZANCOR WHITBY                               | <i></i> v                             |                                       | Lot #: BL                                      | .K 1-3        |              |  |
| Model:   | RLT-01 / STC (BLK 1 UNIT 3,4,                       | 5)                                    |                                       | Phase: Ph                                      | 11            |              |  |
| SERVICE IN                                     | ISTRUCTIONS   | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |                                       |  |               |              |  |
|  | DOOR LN:40 (LEFT) VINYL FRA<br>ER FOR KEY ACCESS ** | AME DAMAC                             | GED                                   |  |               |              |  |
| ADD:<br>REPLACE TH                             | IE MISSED FROSTED SIDE-LI                           | GHT                                   |                                       |  |               |              |  |
| PARTS REC                                      | QUIRED  |                                       |                                       |  |               |              |  |
| LN Item Description Location                   |   |                                       | Specification                         | Size   | Options       | Qty          |  |
| 40 BUCKIN<br>po 82650                          | GHAM PURCH. PATIO DOOR<br>3                         | BKF                                   | FRAME ONLY                            | 71.5 X 95.5                                    | LEFT BK 61316 | 1            |  |
| 121 VINYL CLAD SIDELITES ENT po 80586 po 80717 |   | GLASS ONLY -<br>FIXED                 | 22 X 95.375                           | SDL14 4T/11/4T<br>ACID_ETCH_LOW_<br>*VSL026 BK | _E_ARG        |              |  |
| Problem Desc                                   | ription:  |                                       |                                       |  |               |              |  |
| Warranty                                       |   |                                       | CHARGEABLES                           |  |               |              |  |
| Material \$                                    |   |                                       | □<br>Material \$                      |  |               |              |  |
| Labour \$                                      |   |                                       | Labour \$                             | NIC  |               |              |  |
|  |   |                                       | P.O.#:                                |  |               |              |  |
| Cause:   |   |                                       |                                       |  |               |              |  |
| Solution:                                      |   |                                       |                                       |  |               |              |  |
| -  |   |                                       | *                                     |  | V.            |              |  |
| Date Compl                                     | leted:  |                                       | Appro                                 | oved:  |               |              |  |
| 7  | Time:   |                                       | Service Signs                         | ature:   |               |              |  |
|  |   |                                       | ALEX                                  |  |               |              |  |



Normal

Priority:

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076

SCHEDULED

Status:

WO # W162404 Pack Slip:206644

RELEASED

Service Date: Jan 06, 2023

| BUILDER  |                                       |                     |   |              |  |  |  |
|--|---------------------------------------|---------------------|---|--------------|--|--|--|
| Customer: N000508  | City:                                 | WHITBY              | Received:                                     | Jun 24, 2022 |  |  |  |
| Name: ZANCOR WHITBY  | Service Phone(s)                      | •                   | Time:   |              |  |  |  |
| Service Fax:   | Site Phone:                           |                     | Order:  | D374305-1    |  |  |  |
| Site Fax:  | Lot#:                                 | BLK 1-3             | Phase:  | PH1          |  |  |  |
| RESIDENT INFORMATION   |                                       |                     |   |              |  |  |  |
| Home Owner Name:   | Address                               | s:                  |   |              |  |  |  |
| Home Phone(s):   | Work Pl                               | Work Phone(s):      |   |              |  |  |  |
| Cell Phone(s):   | Email(s                               | ` '                 |   |              |  |  |  |
| LINKED ORDER INFORMATION (D37430   |                                       | ,                   |   |              |  |  |  |
| Customer: N000508 ZANCOR WHITBY  | <b>'</b>                              | Lot #: Bl           | _K 1-3  |              |  |  |  |
| Model: RLT-01 / STC (BLK 1 UNIT 3,4,5)   | ) :                                   | Phase: Ph           |   |              |  |  |  |
| SERVICE INSTRUCTIONS   |                                       |                     |   |              |  |  |  |
| BRK PATIO DOOR LN:40 (LEFT) VINYL FRAN<br>**SEE BUILDER FOR KEY ACCESS **          | ME DAMAGED                            |                     |   |              |  |  |  |
| ADD: REPLACE THE MISSED FROSTED SIDE-LIGH PARTS REQUIRED                           | нт                                    |                     |   |              |  |  |  |
|  | anation Constitution                  | 01                  | Outil no                                      | 24           |  |  |  |
| 40 BUCKINGHAM PURCH. PATIO DOOR E left side jamb repair skin 60-10-0110 po # 78373 | ocation Specification  BKF FRAME ONLY | Size<br>71.5 X 95.5 | Options<br>LEFT BK 61316                      | Qty<br>1     |  |  |  |
| 121 VINYL CLAD SIDELITES po 80586 po 80717   | ENT GLASS ONLY -<br>FIXED             | 22 X 95.375         | SDL14 4T/11/4T<br>ACID_ETCH_LOW<br>*VSL026 BK |              |  |  |  |
| Problem Description: Blinds an   |                                       | to be re            | naoved by                                     | ather's      |  |  |  |
| Warranty   | Parameter                             | CHARGEABLES         |   |              |  |  |  |
| Material \$  | Material                              | Material \$         |   |              |  |  |  |
| Labour \$ Labour \$  |                                       |                     |   |              |  |  |  |
| /  | P.O.#:                                |                     |   |              |  |  |  |
| Cause:   |                                       |                     |   |              |  |  |  |
| Solution:  | 2010                                  |                     |   |              |  |  |  |
|  |                                       |                     |   |              |  |  |  |
| Date Completed   | Apr                                   | proved:             |   |              |  |  |  |
| Time: _//'00 /2.05   | Service Sig                           | nature: 410         | MIKE(RENO)                                    |              |  |  |  |



## Fwd: Brooklin Lot 1-3

2 messages

Melissa Green <mgreen@newmar.com>
To: Shonnessa Facey <sfacey@newmar.com>

Thu, Nov 3, 2022 at 9:26 AM

input please

Forwarded message ————
From: Nathan Simas <nathan@zancorhomes.com>
Date: Thu, Nov 3, 2022 at 7:42 AM
Subject: Brooklin Lot 1-3
To: Melissa Green <mgreen@newmar.com>

Good Morning Melissa

Do we have a service day booked to replace the missed frosted side-light

Thank you,

Nathan Simas

Finishing Supervisor

Now Towns in Brooklin / Belle Aire Shores

Cell # 416-791-9862

nathan@zancorhomes.com



We are making some changes to better serve you. Effective immediately all new service requests are to be sent to servicedept@newmar.com if enquiring about a follow up please email me directly at mgreen@newmar.com

Shonnessa Facey <sfacey@newmar.com>
To: Melissa Green <mgreen@newmar.com>

Thu, Nov 3, 2022 at 9:31 AM

This work order 162404 exists but put on the dummy date. Should I add this to the work order or make a new one? [Quoted text hidden] [Quoted text hidden]

PLEASE NOTE - We are experiencing higher than normal volume and appreciate your patience as we review your inquiry, we are doing our best to respond back in a timely manner. Shonnessa Facey



## Newmar Window Manufacturing Inc.

7630 Airport Road Mississauga, Ontario L4T 4G6 Tel: 905-672-1233 ext.328

Fax: 905-672-1076 Toll Free: 1-800-263-563