



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W181091
Pack Slip:230739

Service Date: Jun 15, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Mar 17, 2023
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D389095-1
Site Fax: Lot#: 328W Phase: 3

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D389095-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 328W
Model: 42-09 TILLER COR/SW Phase: 3

SERVICE INSTRUCTIONS

REPLACE BROKEN GLASS IN MAIN BATH

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
100	NEWMAR VINYL CASEMENT COMPLETED	TW.BTH2/3	GLASS ONLY - SASH	18.75 X 42.75	AG-011B SW/WH LOWE_ARG SW	1
200	NEWMAR VINYL CASEMENT	TW.BTH2/3	GLASS ONLY - SASH	18.75 X 42.75	AG-011B SW/WH LOWE_ARG SW	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$ 120.99

Labour \$ 120

Cause:

Solution:

Date Completed: 6/15/23

Approved:

Time:

Service Signature: KYLE

Lot 328w broken glass

3 messages

Nathan Simas <nathan@zancorhomes.com>

Mon, May 29, 2023 at 11:21 AM

To: Service Department <servicedept@newmar.com>, Melissa Green <mgreen@newmar.com>, Shonnessa Facey <sfacey@newmar.com>

Cc: Carmelo <carmelo@zancorhomes.com>, Chris DiGenova <chris@zancorhomes.com>

Good morning

Master bedroom window pane closet to ensuite

And the window in the twin bath.

Please have this completed by the end of next week, this master bedroom window was already sent.

Thanks,

Nathan Simas

Finishing Supervisor

Belle Aire Shores

Cell # 416-791-9862

nathan@zancorhomes.com


3 attachments



20230529_111335.jpg
2889K



pro-E0UzCaLS.jpeg
791K



out-qcFJMjAO.jpeg
777K

Nathan Simas <nathan@zancorhomes.com>

Mon, May 29, 2023 at 11:27 AM

To: Service Department <servicedept@newmar.com>, Melissa Green <mgreen@newmar.com>, Shonnessa Facey <sfacey@newmar.com>

Cc: Carmelo <carmelo@zancorhomes.com>, Chris DiGenova <chris@zancorhomes.com>

I sent the email too quickly

another pane on the main floor, in the back living room.

Thanks,

Nathan Simas

Finishing Supervisor

Belle Aire Shores

Cell # 416-791-9862

nathan@zancorhomes.com

From: Nathan Simas

Sent: Monday, May 29, 2023 11:21:41 AM

To: Service Department <servicedept@newmar.com>; Melissa Green <mgreen@newmar.com>; Shonnessa Facey <sfacey@newmar.com>

Cc: Carmelo <carmelo@zancorhomes.com>; Chris DiGenova <chris@zancorhomes.com>

Subject: Lot 328w broken glass

[Quoted text hidden]

2 attachments



out-FnfYUpz7.jpeg
798K



pro-bUm10Zix.jpeg
1118K

Melissa Green <mgreen@newmar.com>
To: Shonnessa Facey <sfacey@newmar.com>

Wed, May 31, 2023 at 1:46 PM

input 06.15.2023 kyllle

[Quoted text hidden]

**** IN ORDER TO BETTER SERVE OUR CUSTOMERS, PLEASE NOTE THAT EFFECTIVE IMMEDIATELY ALL NEW SERVICE REQUESTS ARE TO BE SENT TO servicedept@newmar.com *****if inquiring about a follow up please email me directly at mgreen@newmar.com

Thank you. . .

Melissa Green

Customer Service Coordinator

2 attachments

out-FnfYUpz7.jpeg
798K



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W181091
Pack Slip: 230739
Service Date: May 12, 2023

Priority: Normal

Status:

SCHEDULED

RELEASED

BUILDER

Customer: 611313

City:

INNISFIL

Received:

Mar 17, 2023

Name: ZANCOR BELLE AIRE SHORES

Service Phone(s):

Time:

Service Fax:

Site Phone:

Order:

D389095-1

Site Fax:

Lot#:

328W

Phase:

3

RESIDENT INFORMATION

Home Owner Name:

Address:

Home Phone(s):

Work Phone(s):

Cell Phone(s):

Email(s):

LINKED ORDER INFORMATION (D389095-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES

Lot #: 328W

Model: 42-09 TILLER COR/SW

Phase: 3

SERVICE INSTRUCTIONS

REPLACE BROKEN GLASS IN MAIN BATH

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
100	NEWMAR VINYL CASEMENT	TW.BTH2/3	GLASS ONLY - SASH	18.75 X 42.75	AG-011B SW/WH LOWE_ARG SW	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

RAY

3/17/23, 8:30 AM

Newmar / Casa Bella Mail - Fwd: Broken Glass



Christina Pellegrini <cpellegrini@newmar.com>

Fwd: Broken Glass

1 message

Mathew Harant <mharant@newmar.com>

Fri, Mar 17, 2023 at 8:19 AM

To: Christina Pellegrini <cpellegrini@newmar.com>

Zancor belle aire shores

----- Forwarded message -----

From: **Carmelo** <carmelo@zancorhomes.com>

Date: Friday, March 17, 2023

Subject: Broken Glass

To: Mathew Harant <mharant@newmar.com>

Cc: Nathan Simas <nathan@zancorhomes.com>, Chris DiGenova <chris@zancorhomes.com>

Hi Matt

Hope all is well, please see attached picture for lot 328W main bath broken glass.