Purchaser Name: Enrollment: ?????

Jaswinder Singh

Phone Res:

Closing Date: Phone Bus: (416) 434-5599 Inspector: Alexandria Damianidis June 19, 2023

> HOMES ANCOR

Vendor / Builder: Project:

Zancor Homes (Caledon) Ltd. Block 149 Unit 6 / 1

Lot / Phase: Plan:

Municiaplity: Address:

Inspection Date: May 01, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 2

- DAMAGED, INCOMPLETE OR MISSING

  Windows, side lights and other glazing. Window and door screens

  Bathtub sinks and toilets

  Bathroom accessories if provided

  Mirrors, counter tops and cabinetry

  Flooring (hardwood, vinyl, ceramic tiles, carpeting)

  Interior finished and trim carpentry

- Hot water heater, if provided (not rental) Exterior finished, driveways, walkways, decks and landscaping

- OPERATING CONDITION

  Windows, interior and exterior doors. Door locks
  Faucets: Kitchen, bathroom, laundry room
  Exhaust fans (kitchen, bathrooms) if provided
  Electrical outlets and fixtures
  Gas fireplaces, incl.circulation fans, if provided
  Heat Recovery Ventilation system, if provided

- Heating system

  Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

BEDROOM 2 ENSUITE				
VANITY CABINETS	Đ.	CHIP AT BOTTOM GABLE		
MASTER BEDROOM				0
WALK IN CLOSET		BLACK MARKS ON STIPPLE CEILING IN CLOSET	CON REC	1//
FOYER/HALL				
STAIRS		CHIP ON 2ND RISER BELOW NOISING AT STAIRS TO 3RD FLOOR CRACK ON TRIM BY 8TH TREAD AT STAIRS FROM 2ND FLOOR TO LANDING TO 3RD FLOOR STAIN REQUIRED AT MINOR SCRATCH ON 2,3 FLOOR FROM MAIN FLOOR TOO 3RD FLOOR.	Sen e	1 N
KITCHEN				4
CABINETS	3	CHIP ON RIGHT ISLAND GABLE AT FLOOR LINE FACING STAIRS. 2) CHIP ON LEFT GABLE FACING DW AT FLOOR LINE. 3) CHIP ON UPPER LEFT CABINET ABOVE FRIDGE. 4) CHIP AT UPPER GABLE LEFT OF WINDOW. 5) CHIP ON BOTTOM RIGHT PANTRY DOOR	F 00	1
MASTER ENSUITE BATH			3	
FAUCETS/PLUMBING		STANDARD BATH ACCESSORIES NOT SUPPLIED. TO BE LEFT IN HOUSE. DO NOT INSTAL.	1000 C	A
LAUNDRY ROOM				7
CABINETS	39	SCRATCH ON LEFT DOOR BELOW SINK	14.00	V.
POWDER ROOM				7
NOTE:	*	LOWER POWDER - CHIP ON BOTTOM GABLE KICKPLATE		
ELECTRICAL/LIGHTIN	9	SECURE CEILING FAN	N. S. S.	1