



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W182787
Pack Slip:225978

Service Date: Jun 20, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: N000531 City: CALEDON Received: Apr 04, 2023
Name: ZANCOR CALEDON CLUB Service Phone(s): Time:
Service Fax: Site Phone: Order: D386545-1
Site Fax: Lot#: 4B Phase:

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D386545-1)

Customer: N000531 ZANCOR CALEDON CLUB Lot #: 4B
Model: 38-03 BOND (BLK) Phase:

SERVICE INSTRUCTIONS

PATIO DOOR NOT LEVEL NEED RESET
PATIO DOOR SCREEN B/O

Complete

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
60	BUCKINGHAM PURCH. PATIO DOOR BRK		SCREENS-REPLA	29.4375 X	BK 61316 CENTRE OPEN	1
			CEMENT-DOORS	92.375	LEFT BUCKINGHAM PURCH. PATIO DOOR	

Problem Description: *P.D Fixed side installed with no wheels + felt pads backwards*

☐ Warranty

Material \$ _____

Labour \$ _____

☐ CHARGEABLES

Material \$ _____

Labour \$ *NIC*

P.O.#:

no one to sign

Cause: *installation*

Solution: *installed wheels + reversed felt pads installed screens
adjusted patio door to closed + seal*

Date Completed: *June 20/23*

Approved: _____

Time: *2 1/2 hrs*

Service Signature: _____

STEVE



Mar 29
6

NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

Pack Slip #245184

181696

PACKING SLIP

Ship To: ZANCOR CALEDON CLUB
CONCORD

Cust PO #

Plant: N

Estimate: E321109

Slsman: 0038

Customer# N000531

Order D386545-2

Plant: Newmar

Name: ZANCOR HOMES (CALEDON) LTD.

Model: 38-03 BOND (BLK)

Due Date: Mar 29, 2023

Project:

Elev/Gar: B / L

Location: CALEDON

Lot/Phase: 4B

Tags: PART 9

LOCK UP SERVICE

☒
☒
☐
☐
☒
☒
☒

HOUSE READY FOR LOCK-UP

INSTALL ALL SCREENS AND CRANK HANDLES

CHECK OPERATION OF ALL WINDOWS AND DOORS. ADJUST AS NECESSARY

INSTALL PATIO DOOR SCREEN, INSTALL LOCK, CHECK OPERATION

SET SPRING LOADED HINGES ON GARAGE TO HOUSE DOORS

REMOVE SILL COVER AND TAPE FROM ALL DOORS

ISSUES COMPLETED AT LOCK-UP

ROOM/LINE#

☐
☐
☐
☐
☐
☐
☐
☐

Patio doors not level
Need Reset

FOLLOW UP + ISSUES REPORTED

ROOM/LINE#

☐
☐
☐
☐
☐
☐
☐
☐

IMAGE SENT

☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED PC'S IN GOOD ORDER

REC. BY:

*** CLAIMS OF SHORTAGES AND DAMAGE MUST BE MADE AT THE TIME OF DELIVERY ***

MANUFACTURERS OF QUALITY WINDOWS AND ENTRANCE DOOR SYSTEM

SERVICE CHARGE 2% PER MONTH ON OVERDUE ACCOUNTS