



COMP

NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W188034

Pack Slip:243732

Service Date: Jun 23, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000531 City: CALEDON Received: May 31, 2023
Name: ZANCOR CALEDON CLUB Service Phone(s): Time:
Service Fax: Site Phone: Order: D387553-1
Site Fax: Lot#: 95B Phase:

RESIDENT INFORMATION

Home Owner Name: N/A Address: N/A
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D387553-1)

Customer: N000531 ZANCOR CALEDON CLUB Lot #: 95B
Model: 38-04 GRANVIEW (SL)/LOT 95B Phase:

SERVICE INSTRUCTIONS

PRESSURE CRACK - BEDROOM ABOVE FRONT DOOR

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
151	NEWMAR VINYL CASEMENT <i>Done</i>	B3	GLASS ONLY - SASH	18.75 X 62.75	AG13 SL/WH LOWE_ARG SL <i>144.⁰⁰</i>	1
172	NEWMAR VINYL CASEMENT FIXED <i>Done</i>	B2	GLASS ONLY - FIXED	18.75 X 62.75	AG13 SL/WH LOWE_ARG SL <i>144.⁰⁰</i>	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$ *288.⁰⁰*

Labour \$ *120.⁰⁰*

P.O.#:

Cause:

Solution: *Changed Glass units in B3 - B2 due to pressure cracks.*

Date Completed: *June 23/23*

Approved:

Time:

Service Signature: *Mike Clark*

MIKE(RENO)