

120 R.E. Zancor 120

K.Q.C.

Rivers

edge

Key

CHAIR

Steve

Kitchen

- Upper left of Fridge • Top corner of door chipped
- Fridge upper • Door chipped
- Upper right of Fridge • Door chipped
- Upper far left of stove • Ceiling chipped
- Upper right of stove • Door chipped
- Upper far right of stove • Door chipped
- Lower left of Fridge • Shelf chipped
- Lower right of Fridge • Shelf chipped
- Lower left of stove • back of shelf chipped
- Drawers right of stove • Top drawer face chipped
- Lower far right of stove • Front edge rough
- Servory • left upper • door chipped
- Right lower • Door chipped x 2
- Pantry • lower doors (x3) paint chipping @ Inside
- Lower right • Shelf chipped

Master Ensuite

Left door chipped

2nd Ensuite

Shared Bath

Left sink floor chipped

Laundry

- Left gable chipped
- Counter chipped