Enrollment:

Purchaser Name: ?????

Amram Abitbol

Phone Res: (416) 523-8033 Phone Bus: (416) 523-8033 Closing Date: July 20, 2023 Inspector: Alexandria Damianidis HOMES

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 358W / 3

Plan: Address: Municiaplity:

Inspection Date: July 10, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

EXTERIOR			
NOTE:	DOWNSPOUTS NOT INSTALLED		
	GARAGE DOORS NOT INSTALLED		
	BRICK REQUIRED LEFT OF FRONT DOOR DUE TO ELECTRICAL PLUG CHANGE		
	EXTERIOR RAILINGS NOT INSTALLED		
	CAULKING REQUIRED LEFT OF COLD CELLAR ROOM VENT		
	SPRAY FOAM REQUIRED AT RIGHT GARAGE DOOR		
	REMOVE PAINT OFF GARAGE FLOOR		
PORCH	CLEAN MARKS ABOVE FRONT DOOR AS PER HOMEOWNER		
POWDER ROOM			
NOTE:	DOOR DOESNT HAVE LOCK		
UPPER HALL			
FLOORING	STAINS/GLUE MARKS ON RUG IN UPPER HALL MY STAIRS AND BY BATHROOM TUCK CARPET BY STAIRS		<del></del>
MASTER ENSUITE BATH			
FLOORING	STAINS ON RUG AT ENTRANCE TO MASTER		
COUNTERTOPS	REMOVE GLUE MARKS ON LEFT AND RIGHT SIDE SPLASHES	-	
VANITY CABINETS	CHIPS ON BOTTOM GABLE BELOW LEFT SINK		
	CHIPS ON BOTTOM GABLE BELOW RIGHT SINK		
FAUCETS/PLUMBING	SECURE SHOWER HEAD NOT FLUSH		

Enrollment: Purchaser Name: ?????

Amram Abitbol

Phone Res: (416) 523-8033 Phone Bus: (416) 523-8033 Closing Date: July 20, 2023 Inspector: Alexandria Damianidis



Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 358W / 3

Plan: Address: Municiaplity:

Page 2 of 2 Inspection Date: July 10, 2023

KITCHEN		
CABINETS	CHIP ON PANTRY SHELF	 
	UPPER CABINET BOTTOM GABLE NOT FLUSH, CAN SEE WOOD IN 2 AREAS	 
	CHIPS AT BOTTOM GABLE BELOW SINK	 
	CHIPS IN ISLAND CABINET FACING LIVING AREA	 
	CHIPS AT UPPER SHELF RIGHT OF STOVE	 
FLOORING	TILE CUT SHORT BESIDE SLIDING DOOR	 
LIVING ROOM		
NOTE:	FIREPLACE HAS SCRATCHES	 
FOYER/HALL		
NOTE:	CLOSET HANDLE NOT FLUSH	 
BASEMENT		
NOTE:	DUCTS NOT CLEANED	 

A REFERENCE FOR FUTURE WARR	ANTY REQUESTS.  designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHASE their place should ensure they provide written authors.	
I have inspected my new home and I	agree that the description of the items listed	on this form are accurate.	
	<i>M</i> .		
?????	gf ch	Amram Abitbol	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
			AD
		Alexandria Damianidis	, —
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/07/10	July 10, 2023	