Enrollment:

Purchaser Name: Manjinder Singh Dhillon

Kuljit Kaur Dhillon

Phone Res:

Phone Bus: (647) 987-3200 **Closing Date:** July 17, 2023

ZANCOR

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 99B / 1B

Plan: Address: Municiaplity:

Inspection Date: July 13, 2023

Inspector: Alexandria Damianidis Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

FOYER/HALL			·
STAIRS	STAIN REQUIRED AT TRIM AT STAIRS FROM MAIN FLOOR TO SECOND FLOOR DUTY REPLACEMENTS.		
	STAIN REQUIRED LEFT AND RIGHT SIDE AT NOSING AT LANDING TO MUD ROOM		
	BLOTCHY STAIN AT 1 AND 2 TREAD STAIRS FROM MUD ROOM TO MAIN FLOOR.		
	ADJUST TRIM AT OUTSIDE. STRINGER RIGHT OF NOSING UPSTAIRS TO BASEMENT		
	EXPOSE SCREW BELOW, NOSING AT STAIRS A BASEMENT AT RISER		
	TRIM NOT INSTALLED BELOW RISER AT LANDING TO BASEMENT		
	CHIPPER ASTRICAL FRONT PORCH.	-	
WALLO			
WALLS	CAUSE IT INSIDE MY ROOM, DRYWALL UNFINISHED REQUIRED TO BE MUD, SANDED AND PAINTED		
FLOORING	LARGE CHIP ON SIX HARD WOOD PLANK AT SECOND LANDING FROM NOSING UPSTAIRS TO		
	SECOND FLOOR		
DINING ROOM			
ELECTRICAL/LIGHTING	SECURE LIGHT FIXTURE AT CEILING		
WINDOWS	CRACK AT FIXED GLASS WINDOW RIGHT OF OPERATING.		
FLOORING	CHIP ON 10TH HARDWOOD PLANK FROM LEFT ARCHWAY AT ENTRANCE FROM FOYER TO DINNING.		
KITCHEN			
CABINETS	CHIP ON THE LEFT GABLE AT FLOOR LINE LEFT OF STOVE		
	CHIP ON GARBAGE PULL OUT DRAWER RIGHT SIDE		
	CHIP INSIDE UPPER RIGHT, AND LEFT GABLE AT HOODFAN		
	SCRATCH ON BOTTOM RIGHT CABINET AT ISLAND FACING LIVING.		
SHARED ENSUITE			
VANITY CABINETS	LARGE GAP BETWEEN BOTTOM, GABLE AND BACK GABLE BELOW RIGHT SINK		
UPPER HALL			
RAILING	SCREW CAP NOT INSTALLED AT UPPER SHORT RAILING LEFT SIDE		
	STAIN REQUIRED AT 2ND FLOOR RAILING, RIGHT SIDE OF NEWEL POST		

Enrollment:

Purchaser Name: Manjinder Singh Dhillon

Kuljit Kaur Dhillon

Phone Res:

Phone Bus: (647) 987-3200 **Closing Date:** July 17, 2023

Inspector: Alexandria Damianidis



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 99B / 1B

Plan: Address: Municiaplity:

Page 2 of 2 Inspection Date: July 13, 2023

MASTER ENSUITE BATH	I	
NOTE:	SCREEN NOT INSTALLED AT OPERATING WINDOW.	
LAUNDRY ROOM		
CABINETS	CHIP AT BOTTOM GABLE BELOW SINK.	
NOTE:	DRYER VENT STUCK INSIDE WALL.	
BEDROOM #3		
WINDOWS	ADJUST OPERATING WINDOW, NOT CLOSING	
POWDER ROOM		
NOTE:	CHIPS AT BOTTOM GABLE EDGE BELOW SINK.	
LIBRARY/DEN		
WINDOWS	ADJUST RIGHT OPERATING WINDOW, NOT CLOSING	
EXTERIOR		
GARAGE DOORS	GARAGE DOORS NOT INSTALLED	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Manjinder Singh Dhillon

Mundoder singh

Kuljit Kaur Dhillon

Purchaser's Signature

Purchaser's Name (print)

Alexandria Damianidis

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Purchaser's Signature

Date (YYYY/MM/DD)

Purchaser's Name (print)

2023/07/13

July 13, 2023