

31May23	Interval	47	Exterior- General- Pressure wash brick. Clean prior to tinting	Unit-Int 157558	Add	10Jul23	✓ MK
31May23	Interval	48	Exterior- General- Mortar depth not consistent throughout brick. Needs rock bit around the front bricks at the garage area	Unit-Int 157559	Add	10Jul23	
31May23	Interval	49	Exterior- General- Unit-Int to clean the gas piping pipe at exterior	Unit-Int 157560	Add	10Jul23	
09Jul23	Interval	58	Exterior- General- Inspect dent in soffit/Eaves upper left side above garage 2) trim opening upper right corner Soffit at front porch right of Column 3) right side of front porch at side eaves	Tromark Aluminum LTD. 158005	Add	10Jul23	
09Jul23	Interval	59	Stain- General- Stain required at railing from VIP REPAIR	Perfect Touch Painting 158006	Add	10Jul23	✓ MK
09Jul23	Interval	60	Garage- General- Inspect drywall inside garage that was retd when insulation was completed	Foremost Drywall 158007	Add	10Jul23	✓ MK
09Jul23	Interval	61	Garage- General- paint required after deck completed from Foremost	Perfect Touch Painting 158008	Add	10Jul23	
27Jul23	Interval	65	Foyer- General- Patch dents at front door trim paint.	Perfect Touch Painting 158467	Add	10Jul23	✓ MK
27Jul23	Interval	66	Foundation- General- Svc - fill gap at foundation wall in between garage doors and eul poly.	Vasquez Zanacor Wreck Service 158468	Add	10Jul23	✓ MK
27Jul23	Interval	67	Garage- General- adjust garage doors like coming through a Bottom.	Abbey Overhead Doors Inc. 158469	Add	10Jul23	

Homeowner Signature: 

The Homeowner acknowledges and accepts that all initiated work has been completed in a workman like manner to their satisfaction.

Date: July 10, 2023

Zanacor Service Technician: 