Enrollment:

Purchaser Name: Roberto, A Marasigan

Aileen Marasigan

Phone Res: (705) 977-2666 Phone Bus: (289) 234-0469 Closing Date: July 27, 2023 Inspector: Gisella Fiore

HOMES

Page 1 of 2

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 53W / 3

Plan: Address: Municiaplity:

Inspection Date: July 20, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

EXTERIOR		
NOTE:	REMOVE PLASTER OFF GARAGE FLOOR SLAB	
	SECURE PLUG AT FRONT DOOR.	
	CHIP AT 1 7 PRECAST AND SIDE EDGE.	
	EXPOSED HOLE LEFT OF STAIRS.	
	REMOVED BLACK MARKS OFF STONE RIGHT OF PORCH	
	COLD ROOM VENTS NOT INSTALLED	
SHINGLES	TORN SHINGLES AT ROOF ABOVE LEFT GARAGE PEAK. CAN SEE FROM WINDOW INSIDE.	
SHARED ENSUITE		
WALLS	SALMON, CRACK AT OPERATING WINDOW ABOVE TOILET	
KITCHEN		
CABINETS	CHIP INSIDE BOTTOM GARBAGE PULL OUT AND RIGHT AND LEFT CABINET BELOW SINK	
	CHIP AT UPPER VALANCE, LEFT THE FRIDGE AT CORNER	
	CHIP ON UPPER RIGHT CABINET RIGHT OF HOOD FAN AT BOTTOM RIGHT CORNER	
	MULTIPLE CABINETS THROUGHOUT NOT SOFT CLOSE. (UPPER RIGHT CABINET RIGHT OF	
	HOODFAN , ALL CABINETS AT ISLAND, UPPER LEFT CABINET LEFT OF HOODFAN.).	
	CHIP ON FIRST PULL OUT POT DRAWER BELOW COOKTOP.	
WINDOWS	CHIP ON HANDLE AT SLIDING DOOR	
COUNTERTOPS	SOAP DISPENSER NOT INSTALLED AT ISLAND INSTALL 6 INCHES RIGHT OF FAUCET	
SINK/FAUCET/PLUMBING	BOTTOM SINK GRID AS PER EXTRAS NOT INSTALLED.	
MASTER ENSUITE BATH		
VANITY CABINETS	CHIP AT BOTTOM RIGHT RIGHT CABINET BELOW RIGHT SINK AND RIGHT GABLE EDGE	
	CHIP AT 2,4 BANK OF DRAWER	
	CHIP AT BOTTOM LEFT CABINET LEFT OF SINK.	
FAUCETS/PLUMBING	SHOWER HEAD NOT INSTALLEDD.	

Enrollment:

Purchaser Name: Roberto, A Marasigan

Aileen Marasigan

 Phone Res:
 (705) 977-2666

 Phone Bus:
 (289) 234-0469

 Closing Date:
 July 27, 2023

 Inspector:
 Gisella Fiore

ZANCOR HOMES PDI

Page 2 of 2

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Inspector's Signature

Lot / Phase: 53W / 3 Plan:

Address: Municiaplity:

Inspection Date: July 20, 2023

MASTER ENSUITE BATH			I
FLOORING	INSPECT WALL TILE IN SHOWER WHERE SHOWER HEAD WAS MOVDED - TILES RAISED.	 	
UPPER HALL			
WALLS	LINE IN STIPPLE ABOVE STAIRS.	 	
BEDROOM #2			I
WALLS	RIPPLE AT CORNER LEFT SIDE AT HIGH CEILING.	 	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Roberto, A Marasigan

Purchaser's Name (print)

Purchaser's Signature

Purchaser's Signature

Gisella Fiore

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Date (YYYY/MM/DD) 2023/07/20 July 20, 2023