Outstanding Deficiencies Rivers Edge - Phase: 1 - Lot: 44

<u>10Jul23</u>	10Jul23	10Ли123	10Jul23	10Jul23	10Jul23	10Jul23	10Jul23	10Jul23	<u>10Jul23</u>	<u>10Jul23</u>	10Jul23	10Jul23	10Jul23	<u>Date</u> <u>Reported</u>
PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	PDI	Туре
14	13	12	11	10	9	00	7	6	O ₁	4	w	2	<u></u>	Number
FOYER/HALL-STAIRS~CHIP ON THIRD AND FOURTH OUTSIDE STRINGER TREAD AT STAIRS FROM MAIN FLOOR TO LANDING TO SECOND FLOOR AND SEE FROM BASEMENT STAIRS	FOYER/HALL- STAIRS~CHIP AT RIGHT NEWEL POST AT EDGE AT STAIRS AT MAIN FLOOR	FOYER/HALL- FLOORING~CHIP AT 4TH HARDWOOD PLANK FROM LEFT NEWEL POST AT MAIN FLOOR BELOW STRINGER	FOYER/HALL- FLOORING~CHIP ON FIFTH HARDWOOD PLAYING FROM LEFT WALL BELOW ARCH AT ENTRANCE TO MUD ROOM	KITCHEN- CABINETS~CHIP AT 3RD BANK OF DRAWER	KITCHEN- CABINETS~CHIP AND BOTTOM GABLE AT CORNER CABINET LEFT OF STOVE AND SHELF	KITCHEN- CABINETS~MISSING SHELF AT LEFT SIDE OF ISLAND CABINET	KITCHEN- CABINETS-CHIPS ON LEFT ISLAND AND RIGHT GABLE AT FLOOR LINE AND TRIM AT RIGHT AND LEFT SIDE OF THE ISLAND GABLES WRONG PUTTY USE TO FILL HOLES	MASTER ENSUITE BATH- SHOWER ENCLOSURE~SCRATCH ON MARBLE JAMB	SHARED ENSUITE- VANITY CABINETS~CHIP INSIDE BOTTOM RIGHT GABLE BELOW RIGHT SINK.	SHARED ENSUITE- NOTE:~HOMEOWNER REQUESTING TO INSPECT DOOR TO SHARE BATH FOR BUBBLE.	BEDROOM 3 ENSUITE- FLOORING~TILE INSTALLED RIGHT OF VANITY	BEDROOM 3 ENSUITE- SHOWER ENCLOSURE~SCRATCHES A ON MARBLE JAMB	BASEMENT- NOTE:~BASEMENT WINDOW SCREENS MISSING THROUGHOUT	Deficiency Description
Bolton Railings Inc. 158969	Bolton Railings Inc. 158968	First Canadian Hardwood 158967	First Canadian Hardwood 158966	New Image Kitchens 158965	New Image Kitchens 158964	New Image Kitchens 158963	New Image Kitchens 158962	Metropolitan 158961	New Image Kitchens 158960	WYECROFT TRIM 158959	AV Classic 158958	Metropolitan 158957	Wasaga Zancor Site Labour 158956	<u>Trade</u> <u>Assigned</u>
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	Add Appointment Date
7	+	t	+	<		×		<	<		<	<	<	Item Completed
				3	3		3	3	3	圣	更	3	?	Initial

* ZWO ENS -CUERY GROUT FROM THE RIGHT OF VAN I

10Jul23	10Jul23	10Jul23	10Jul23
PDI	PDI	PDI	PDI
<u></u>	17	16	15
EXTERIOR-PORCH~REPLACE STEPS AT FRONT, PITTED	EXTERIOR- NOTE:~REMOVE PAINT OFF GARAGE FLOOR	FOYER/HALL- STAIRS-VARNISH REQUIRED AT TRIM LEFT SIDE AT 1ST LANDING AND AT RISER BELOW	FOYER/HALL- STAIRS-CHIP ON OUTSIDE STRINGER AT FOURTH 6TH AND SEVENTH TREAD AT STAIRS FROM LANG TO SECOND FLOOR
Wasaga Zancor Site Labour 158973	Perfect Touch Painting 158972	Perfect Touch Painting 158971	Bolton Railings Inc. 158970
Add	Add	<u>Add</u>	Add
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint,
N SEE	4		*
De la companya de la	Y	P	

Ξ	
B	
eo	
WI	
P	
Si	
gna	
E	
ie.	

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Zancor Service Technician:

VSHARD BATH-SWALLENP @ CENTER OF SINICS @ CONTER VARIATO FAMILY- TUP PAINT (SANDOUT FRST) A80

* SPEAK TO GISELUA PROUT GRAIN OF WOOD
SHOWING @ WINDOW CASINGS*



The items listed below were released to the homeowner(s) of

Lot # Site/Phase:	Shoreline Point
√ House and Garage Door Keys	
Homeowner Manual (given at PDI)	
_N/A Recycling and Green Bins	
N/A Other	
The above items were received on this $\partial \mathcal{O}$ day of _	JULY , 2023
D	
Purchaser	Purchaser