BUILDER:	
Zancor Homes	
JOB SITE:	
Caledon Club	

Customer Code: Job Number: 18338 Board Area:8

COMPLAINT DATE: 07/04/23 L01:

157B

INSTALLER: SCHEDULED DATE: 07/31/23

OWNER NAME: OWNER TEL:

OWNER ADDR: REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE: E-MAIL

PO Required:

NO

Inspection Reqd:

NO

**BUILDER WO#** 

BUILDER PO#:

REPAIRMAN:

**ORIGINAL WO#:** 695235

REPAIR DESC: Adjust carpet shims throughout second floor

PROD ORDERED: PROD INFO/NOTES:

SUPPLIER:

PO#:

**DUE: /0/** 

INSTALLER'S SIGNATURE:

SUPER'S/OWNER'S SIGNATURE: holaton williams

DATE: July 2184 . 2023

NOTE\*\*\* Please have this memo signed by the owner or site super upon completion.

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



















































BUILDER:	
Zancor Homes	
JOB SITE:	
Caledon Club	

Customer Code: Job Number: 18338 Board Area:8

COMPLAINT DATE: 07/13/23 <u>[</u> 101B

**INSTALLER:** 

OWNER TEL:

SCHEDULED DATE: 07/31/23

OWNER NAME: (647) 643-1043

OWNER ADDR: **Camino Real Drive** 112 Camino Real Drive 112 REPAIR TYPE: **REPAIR DURATION: 0** PD

ACCESS NOTES:

**BUILDER WO#** 

REPAIRMAN: PO Required:

**BUILDER PO#**:

REPAIR DESC: Bedroom 3 - Adjust carpet shims at entrance to bath and closet left side

**ORIGINAL WO#:** 

691213

Ö

Inspection Reqd:

NO O

Bedroom 2 - Adjust carpet shims both entrances

Master Bedroom - Adjust carpet shim at entrance to master and at bathroom

PROD ORDERED: PROD INFO/NOTES:

SUPPLIER:

PO#:

**DUE: /0/** 

INSTALLER'S SIGNATURE:

NOTE\*\*\* Please have this memo signed by the owner or site super upon completion.

SUPER'S/OWNER'S SIGNATURE:

DATE:

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

DATE

INSTALLER SIGNATURE



PROTECTION



































