Enrollment: Purchaser Name: ????

Phone Res:

Rishi Bhalla

Phone Bus: (416) 464-0068

Closing Date: August 10, 2023 Inspector: Gisella Fiore

HOMES

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 348W / 3

Plan: Address: Municiaplity:

Inspection Date: July 31, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

| EXTERIOR | | |
|---------------------|--|-----------------|
| GARAGE DOORS | GARAGE DOOR IS NOT INSTALLED | |
| NOTE: | HARDY BOARD AT FRONT PORCH PEAK, NOT COMPLETE | |
| FOYER/HALL | | |
| STAIRS | STINA REQUIRED, I TRIM AT MAIN FLOOR AND LANDING | |
| LIVING ROOM | | |
| NOTE: | FIRE PLACE NOT INSTALLED. | |
| FLOORING | CHIP AT 18, 41 PLANK FROM WALL LEFT OD FIREPLACE. | |
| MASTER ENSUITE BATH | | |
| VANITY CABINETS | CHIP AT BOTTOM LEFT GABLE BELOW LEFT SINK AND SECURE RIGHT GABLE BELOW RIGHT SINK. | - |
| FLOORING | AS PER HOMEOWNER REQUESTING FLOOR TO BE DARK GROUT SINCE TILE ARE DARK | |
| UPPER HALL | | |
| RAILING | STAIN REQUIRED AT JULIET, BALCONY, RAILING, AND STAIN REQUIRED AT SCREW PLUGS | |
| FLOORING | SMALL CHIP ON 7TH HARDWOOD PLANK FROM WALL LEFT OF MASTER BEDROOM. | |
| SHARED ENSUITE | | |
| VANITY CABINETS | CHIP INSIDE BOTTOM LEFT GABLE BELOW SINK | |
| BEDROOM 4 ENSUITE | | |
| VANITY CABINETS | CHIP ON LEFT COUNTERTOP EDGE | |
| BEDROOM #4 | | |
| FLOORING | SQUEAK BELOW CARPET LEFT OF WINDOW AT CORNER AND MIDDLE BELOW LIGHT FIXTURE. | |
| BASEMENT | | |
| NOTE: | DUCTS. NOT CLEANED | |
| | ADJUST OPERATING WINDOW NOT CLOSING. | |
| | NO HOT WATER THROUGHOUT | |
| | | |

Enrollment: Purchaser Name: ????

Phone Res:

Rishi Bhalla

Phone Bus: (416) 464-0068

Closing Date: August 10, 2023

ZANCOR

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 348W / 3

Plan: Address: Municiaplity:

Page 2 of 2 Inspection Date: July 31, 2023

Inspector: Gisella Fiore KITCHEN CABINETS CHIP INSIDE BOTTOM GABLE AT ISLAND BELOW SINK CHIP INSIDE BOTTOM RIGHT GABLE AT LOWER CABINET RIGHT OF STOVE NOTE: SVC TO REMOVE FILM AT JOINT OF COUNTERTOP LEFT OF STOVE.

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. ???? Rishi Bhalla Purchaser's Name (print) Purchaser's Signature Purchaser's Signature Purchaser's Name (print) Gisella Fiore Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature Date (YYYY/MM/DD) 2023/07/31 July 31, 2023