Enrollment:

Purchaser Name: Manjinder Singh

HOMES

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 36B / 1B

Plan: Address:

Municiaplity:

Inspection Date: August 01, 2023

Phone Res: Phone Bus:

Closing Date: August 03, 2023

Inspector: Alexandria Damianidis

Page 1 of 2

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
CABINETS	CHIPS AT 1ST BANK OF DRAWERS RIGHT OF STOVE	
	CHIP ON FILLER PIECE LEFT OF FRIDGE	
	CHIP ON 2ND BANK OF DRAWERS LEFT SIDE	
MASTER ENSUITE BATH		
VANITY CABINETS	CHIPS ON BOTTOM GABLE BELOW LEFT SINK	
	CHIPS ON BOTTOM GABLE BELOW RIGHT SINK 2) REMOVE PAINT ON CABINETS	
FLOORING	REMOVE GLUE OFF FLOOR	
FAUCETS/PLUMBING	UPGRADED BATH ACCESSORIES NOT SUPPLIED OR INSTALLED THROUGHOUT. INSTAL BASED	
	ON PHOTOS LOCATIONS (SITE)	
SHOWER ENCLOSURE	INSPECT DIRT BY POT LIGHT IN SHOWER	
GENERAL COMMENTS		
NOTE:	TOUCH UP DOOR FRAMES THROUGH OUT - ROUGH	
SHARED ENSUITE		
NOTE:	SHARED ENSUITE DOOR HARD TO OPEN AND CLOSE ALSO DOOR IN BEDROOM 2	
BEDROOM 3 ENSUITE		
VANITY CABINETS	CHIP ON BOTTOM GABLE LEFT SIDE	
LAUNDRY ROOM		
FLOORING	REMOVE GLUE FROM LAUNDRY FLOOR 2)REMOVE PAINT ON LAUNDRY SINK 3) CLEAN	
	LAUNDRY SINK DIRTY	
CABINETS	CHIP ON BOTTOM GABLE LEFT SIDE AND INSPECT SCRATCHES ON LEFT GABLE	
FOYER/HALL		
NOTE:	DENTS IN GARAGE MAN DOOR	
	INSPECT AC THROUGHOUT, SOME ROOMS NOT AS STRONG AS OTHERS	
FLOORING	CHIP ON 12TH HARDWOOD PLANK FROM LEFT WALL AT FOYER AND ON 20TH PLANK 25TH	
FRONT DOORS	CHIP/WOOD SHOWING BY FRONT DOOR LOCK	

Enrollment:

Phone Res:

Phone Bus:

Purchaser Name: Manjinder Singh

Closing Date: August 03, 2023

Inspector: Alexandria Damianidis

ZANCOR HOMES PDI Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 36B / 1B

Plan:

Address: Municiaplity:

Page 2 of 2 Inspection Date: August 01, 2023

FOYER/HALL		
WALLS	BLACK MARK ON CEILING AT FRONT DOOR	
BASEMENT		
NOTE:	HUMIDIFIER NOT CONNECTED	
UPPER HALL		
FLOORING	CHIPS FILLED IN UPPER HALL, REALLY NOTICEABLE AND DON'T LOOK GOOD. HOMEOWNER REQUESTING TO HAVE THIS FIXED/REPLACED - ON 7TH, 10, 11,12 HARDWOOD PLANK FROM STAIRS IN UPPER HALL	
EXTERIOR		
NOTE:	CAULKING MISSING AT COLD CELLAR VENT BOTH SIDES OF HOME CAULKING MISSING AT DRYER VENT TOP LEFT SIDE OF HOME CHIPS AT FIRST AND 2ND STEP CHIP ON WALK WAY FLASHING ABOVE GARAGE BOWED	
GARAGE DOORS	SCRATCH ON LEFT GARAGE DOOR AND ON RIGHT DOOR	

A REFERENCE FOR FUTURE WAR	RANTY REQUESTS. To designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHAS neir place should ensure they provide written auth	
I have inspected my new home and	I agree that the description of the items listed	on this form are accurate.	
	(Sp)		
Manjinder Singh			
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Alexandria Damianidis	AD
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (VVVV/MM/DD)	2023/08/01	August 01 2023	