Outstanding Deficiencies Rivers Edge - Phase: 1 - Lot: 37

<u>20Jul23</u>	20Jul23	<u>20Jul23</u>	20Jul23	20Jul23	20Jul23	Date Reported
PDI	PDI	PDI	PDI	PDI	PDI	Туре
6	5	4	ω	2	1	Number
Exterior- General- inspect siding at rear and left side of house (wavy)	Exterior- General- install rear light	Exterior- General- touch up paint at front door frames	Main Bathroom- General- bsmt bath - touch up grout at shower floor tiles	Main Bathroom- General- basement bath - requires vanity	Kitchen- General- gable right of dishwasher, touch ups required at floor line and remove shim	Deficiency Description
Trudel And Sons Roofing Ltd. 159735	Mykon Electric North Ltd 159734	Wasaga Zancor Site Labour 159733	AV Classic 159732	New Image Kitchens 159731	New Image Kitchens 159730	Trade Assigned
Add	Add	Add	Add	Add	Add	Add Trade
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	Add Appointment Trade Date
X	XH	7	XIX	17K	Z.	Item Completed
						Initial

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: 194423

Date: Zancor Service Technician:

ADD BOUT VANITY SUNK KANCET.



The items listed below were released to the homeowner(s) of	
---	--

Purchaser	Reco	he above items were received on this 4th day of Augus	N/A_ Other	N/A_ Recycling and Green Bins	^ Homeowner Manual (given at PDI)	House and Garage Door Keys	Lot # 37 Site/
Purchaser		day of August 2023					Site/Phase:River's Edge