

Laura Polsinelli

ZANCOR caledon 153-2

From: Domenic DiGenova
Sent: Wednesday, July 26, 2023 8:49 AM
To: Beata Slipska; Laura Polsinelli; Anthony Petta; Anthony Riccardi
Subject: FW: 153-2 caledon qc

Aug 1
KEY
Prest.

Team,

Please work towards cleaning up these Q/C item before PDI



Domenic DiGenova
VP Of Construction
221 North Rivermede Road
Concord, Ontario
L4K 3N7
T. 905.738.7010
F. 905.738.5948

0607

From: Chris DiGenova <chris@zancorhomes.com>
Sent: Wednesday, July 26, 2023 8:49 AM
To: Domenic DiGenova <domenic@zancorhomes.com>; Anthony Riccardi <anthony@zancorhomes.com>
Subject: 153-2 caledon qc

Master ens:

All tiles in shower not straight
Top left corner of shower grout gap
Glue stain right cabinet
GFI crooked
Grout at threshold gap

AV
AV
NZ
DE
AV.

Dome

Master:

Balcony wood not straight
Bolt crack at wlc door
Left heat register not flush with ground
Hardwood touch ups tape
Groove in hardwood taped
Adjust balcony doors

CWD.
VT.
ZAW.
FCH.
FCH.
NW.

Main:

Dap side splash to wall

Glue stain on middle and left cabinet
Kick plate not flush with tile
Fan hitting housing

NI
NI

DE

Bed 2:

Small hole in cathedral ceiling drywall
Tape crack right side cathedral ceiling

FD
FD

Bed 3:

Damage at wic door

VT.

Don't

Stairs

Far right of landing drywall tape crack

FD

Powder room:

No lock

VT

Stain in grout by toilet

ZAN.

Kitchen

Glue stain in cab left of dishwasher

NI

Chip in lower gable garbage cabinet

NI

Chip in shelf right of sink

NI

Chip at upper gable above stove

NI

Chip at upper gable upper cabinet left of stove

NI

Exterior wood visible left side of garage balcony

PM.