



Quality Sterling Group

Mike

REPAIR ORDER
744889



PO

BUILDER: Zancor Homes JOB SITE: Caledon Club
Customer Code: Job Number: 18338 Board Area: 8
COMPLAINT DATE: 07/20/23 LOT: 49B
INSTALLER: SCHEDULED DATE: 08/15/23
OWNER NAME: OWNER TEL:
OWNER ADDR: REPAIR DURATION: 0
ACCESS NOTES: REPAIR TYPE: E-MAIL
REPAIRMAN: BUILDER WO#
BUILDER PO#: TBA PO Required: YES Inspection Req'd: NO
ORIGINAL WO#: 697320
REPAIR DESC: Master Bedroom - Adjust carpet shim at entrance to bathroom
Master Bedroom - Carpet has dirt spot. Remove if possible
Shared Bathroom - Adjust carpet shims at both entrances to bathroom
Shared Bathroom - Carpet has dirt spot. Remove if possible

PROD INFO/NOTES:
PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE: _____

SUPER'S/OWNER'S SIGNATURE: _____

DATE: _____

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

