



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W189994
Pack Slip:234053

Service Date: Aug 09, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000531 City: CALEDON Received: Jun 21, 2023
Name: ZANCOR CALEDON CLUB Service Phone(s):
Service Fax: Site Phone: Time:
Site Fax: Lot#: 145B Order: D392077-1
Phase: 1B

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D392077-1)

Customer: N000531 ZANCOR CALEDON CLUB Lot #: 145B
Model: 30-02 CABO (OPT. 4BED) (SL)/LOT 145B Phase: 1B

SERVICE INSTRUCTIONS

G-ROOM-70 WINDOW OP PANEL GLASS BROKEN 96X68 H/L

ADD:
PATIO DOOR WILL NOT LOCK (LINE: 60)
- FRONT DOORLITE FRAME IS MISSING THE SCREW CAP COVER (LINE: 122)

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
71	NEWMAR VINYL CASEMENT	G.ROOM	GLASS ONLY - SASH	18.75 X 62.75	CLR LOWE_ARG SL	1
122	E620C_STYLE DOORLITE CUSTOM SCREW CAP COVER	ENT	OTHER RPLCMNT PARTS	22 X 48	E620C_STYLE DOORLITE CUSTOM	2

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$ 112

Labour \$ 120

P.O.#:

Cause:

Solution:

Date Completed: Aug 9, 2023

Approved: [Signature]

Time:

Service Signature: [Signature]

ZAHER



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W189994
Pack Slip:234053

Service Date: Aug 09, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000531 City: CALEDON Received: Jun 21, 2023
Name: ZANCOR CALEDON CLUB Service Phone(s): Time:
Service Fax: Site Phone: Order: D392077-1
Site Fax: Lot#: 145B Phase: 1B

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D392077-1)

Customer: N000531 ZANCOR CALEDON CLUB Lot #: 145B
Model: 30-02 CABO (OPT. 4BED) (SL)/LOT 145B Phase: 1B

SERVICE INSTRUCTIONS

G-ROOM-70 WINDOW OP PANEL GLASS BROKEN 96X68 H/L

ADD:
PATIO DOOR WILL NOT LOCK (LINE: 60)
- FRONT DOORLITE FRAME IS MISSING THE SCREW CAP COVER (LINE: 122)

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
71	NEWMAR VINYL CASEMENT	G.ROOM	GLASS ONLY - SASH	18.75 X 62.75	CLR LOWE_ARG SL	1
122	E620C_STYLE DOORLITE CUSTOM SCREW CAP COVER	ENT	OTHER RPLCMNT PARTS	22 X 48	E620C_STYLE DOORLITE CUSTOM	2

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

ZAHER



Tim Maldonado <tmaldonado@newmar.com>

WO # W189994

1 message

Mathew Harant <mharant@newmar.com>
To: Tim Maldonado <tmaldonado@newmar.com>

Fri, Jul 28, 2023 at 8:21 AM

Hi Tim,

Can you please add to this SWO:

Patio door will not lock (line: 60)
Front doorlite frame is missing the screw cap cover (line: 122)

Thank you,

Mathew Harant
Sales Account Manager

Newmar Window Manufacturing Inc.

7630 Airport Road

Mississauga, Ontario L4T 4G6

Tel: 905-672-1233

Fax: 905-672-1076

Toll Free: 1-800-263-5634

www.newmar.com

[Click here for information on Newmar Aluminum Window Wall systems](#)

Manufacturers of Quality Windows and Entrance Door Systems

Please consider the environment before printing this email.

This e-mail and any attachments may contain information that is privileged and/or confidential. If you are not the intended recipient and appear to have received this e-mail in error, please notify us immediately and then delete all copies from your computer system. Any unauthorized use, copying or further distribution is prohibited. Please also note that if you send us e-mails containing time-sensitive or important instructions, you should ensure that receipt has been timely acknowledged in view of the potential for misdirection or inadvertent interception. Thank you.





Service Department <servicedept@newmar.com>

Fwd: Zancor caledon lot 145B

1 message

Melissa Green <mgreen@newmar.com>
To: Service Department <servicedept@newmar.com>

Wed, Jun 21, 2023 at 1:56 PM

----- Forwarded message -----

From: **Louie Tesoro** <tesorotruck13@gmail.com>
Date: Wed, Jun 21, 2023 at 1:01 PM
Subject: Zancor caledon lot 145B
To: Newmar <service@newmar.com>
Cc: Tesoro <tesorowindows@bellnet.ca>, Ted <t Schlosser@newmar.com>

G-room-70 window op panel glass broken 96x68 H/L

**** IN ORDER TO BETTER SERVE OUR CUSTOMERS, PLEASE NOTE THAT EFFECTIVE IMMEDIATELY ALL NEW SERVICE REQUESTS ARE TO BE SENT TO servicedept@newmar.com *****if inquiring about a follow up please email me directly at mgreen@newmar.com

Thank you 😊

Melissa Green
Customer Service Coordinator



20230621_120250.jpg
1794K