

Zancor Homes (Caledon) Ltd. Warranty Services

Fax: (905) 738-5948 Phone: (905) 738-7010

Closing Date: 17Jul23

Address:

Caledon Club - Phase: 1B - Lot: 100B

Today's Date: Location:

Contact(s): Rajinder Singh Bhullar - Cell: (647) 629-9842 - (rajinder.bhullar@yahoo.com) Ravinder Kaur Bhullar - Cell: (647) 857-9842 - (rajinder.bhullar@yahoo.com) rajinder.bhullar@yahoo.com 10Aug23

Email:

Company: Abbey Overhead Doors Inc

Attention:

Telephone: (905) 497-7677 (905) 497-7577

DAI	Type	DAI Type Issue	
160994	Interval	Garage- General- Garage doors are hard to open, stuck most of the time.	ard of

Date Completed:

Trade &/or Service Tec

has been completed in a workman like manner.

The Homeowner acknowledges and accepts all work

Homeowner Signature:

Date Completed: __

Signature:

Print Name:

appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. Please schedule your Service Department to complete work on the above Lot. Should no

it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and

applied to the Company listed above.

12-for Confirmed