



**Zancor Homes (Caledon) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date: 03Aug23**

**Address:**

**Location: Caledon Club - Phase: 1B - Lot: 34B**

**Today's Date: 09Aug23**

**Contact(s): Preet Sharma - Cell: (416) 300-5664 - (preetsrma@gmail.com)**

**Pooja Sharma - Cell: (416) 294-9728 - (virgo.chemistry@gmail.com)**

**Email: preetsrma@gmail.com**

**Company: Promark Aluminum LTD.**

**Attention: Kamar Kuyumju - Cell: 416-576-0236**

**Telephone: (905) 857-5692**

**Fax: (905) 857-5961**

**Please Complete the following items:**

DAI	Type	Issue	Appt. Date/Time	Notes
160381	PDI	EXTERIOR- PORCH~DENT ON SOFFIT LEFT OF RIGHT COLUMN		
160383	PDI	EXTERIOR- NOTE:~SOFFIT DAMAGE BELOW EAVES. RIGHT SIDE OF HOUSE ABOVE GARAGE		

**Date Completed:** \_\_\_\_\_

**Homeowner Signature:** \_\_\_\_\_

The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

**Date Completed** 08/28/2023

**Trade &/or Service Tech.** \_\_\_\_\_

**Signature:** \_\_\_\_\_

**Print Name:** \_\_\_\_\_

Please schedule your Service Department to complete work on the above Lot. Should no  
appointment time or date appear (below) on this form, it is your responsibility to arrange and  
adhere to the appointment you have scheduled. Your service representative must have this form  
signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Caledon Club - Phase: 1B - Lot: 34B**

**160381 - 1 - PORCH-DENT ON SOFFIT LEFT OF  
RIGHT COLUMN**



**160383 - 1 - NOTE:-SOFFIT DAMAGE BELOW  
EAVES. RIGHT SIDE OF HOUSE ABOVE GARAGE**

