

Outstanding Deficiencies

Now Towns In Brooklyn - Phase: 1 - Lot: Unit 14 (Block 2)

Date Reported	Type	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date	Item Completed	Initial
08Aug23	1 Year	1	Den- General- drywall seams and joint are uneven and visible on main floor	Roomcraft Drywall 160703	Add	29Aug23		
08Aug23	1 Year	2	Poyer- General- unpainted ceiling - svc	Brooklyn Zancor Warranty Service 160704	Add	29Aug23	✓	CC
08Aug23	1 Year	3	Bedroom 2- General- drywall fell off and wall uneven -svc	Brooklyn Zancor Warranty Service 160705	Add	29Aug23		
08Aug23	1 Year	4	Bedroom 2- General- unpainted wall after repair - svc	Brooklyn Zancor Warranty Service 160706	Add	29Aug23	✓	CC
08Aug23	Interval	13	Den- General- 1st Floor/Office - cracked and uneven wall - svc	Brooklyn Zancor Warranty Service 160707	Add	29Aug23		
08Aug23	Interval	14	Upper Hall- General - 2nd Floor - unpainted wall after repair - svc	Brooklyn Zancor Warranty Service 160708	Add	29Aug23	✓	CC
08Aug23	Interval	15	Master Bedroom- General- Cracked and uneven wall in Primarily bedroom -svc	Brooklyn Zancor Warranty Service 160709	Add	29Aug23		

Homeowner Signature: 

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: 8/29/23

Zancor Service Technician: 