Enrollment:

Purchaser Name:

Shankara, Nikhil Rachwani

Phone Res:

Phone Bus: (437) 229-0095 Closing Date: September 07, 2023 Inspector: Alexandria Damianidis

HOMES

Page 1 of 2

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 357W / 3

Plan: Address: Municiaplity:

Inspection Date: August 29, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

LAUNDRY ROOM		
WALLS	DRYWALL MISSING AT DRYER VENT	
	TILE BASEBOARD MISSING AT DRYER VENT	
MASTER ENSUITE BATH		
FAUCETS/PLUMBING	UPGRADED BATH ACCESSORIES NOT SUPPLIED THROUGHOUT. SITE TO INSTAL BASED ON PHOTOS	
VANITY CABINETS	CHIPS AT BOTTOM GABLES BELOW LEFT SINK 2) TIGHTEN ALL VANITY CABINETS THROUGHOUT, LOOSE	
SHARED ENSUITE		
VANITY CABINETS	CHIPS AT BOTTOM GABLES BELOW SINK	
	CHIP AT LEFT SIDE SPLASH	
BEDROOM 2 ENSUITE		
VANITY CABINETS	CHIP AT BOTTOM LEFT GABLE BELOW SINK 2) CHIPS ON SIDE SPLASH	
FOYER/HALL		
STAIRS	DISCOLOURATION ON 7TH TREAD AT STAIRS FROM FIRST FLOOR TO 1ST LANDING ALSO ON 2ND TREAT FROM 1ST LANDING AT STAIRS TO 2ND FLOOR	
FRONT DOORS	CHIPS ASTRICAL AT FRONT DOOR	
MASTER BEDROOM		
WINDOWS	WINDOW SCREENS AND CRACKS NOT INSTALLED THROUGHOUT	
WALLS	OVER CUT IN WALK IN CLOSET AT LIGHT	
POWDER ROOM		
FLOORING	TILE NOT CUT BIG ENOUGH, VENT NOT FITTING INSIDE	
WALLS	SETTLEMENT CRACK BELOW WINDOW	

Enrollment: Purchaser Name: ?????

Shankara, Nikhil Rachwani

Shankara, Nikhil Ra

Phone Res:
Phone Bus: (437) 229-0095
Closing Date: September 07, 2023
Inspector: Alexandria Damianidis



Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 357W / 3

Plan: Address: Municiaplity:

Page 2 of 2 Inspection Date: August 29, 2023

KITCHEN		
CABINETS	SECURE HANDLE OF 3RD BANK OF DRAWERS	
	CHIP AT BOTTOM GABLE BELOW SINK	
	STAPLE IN ISLAND CABINET GABLE	
	KICKPLATE/GABLE NOT COMPLETE BESIDE SINK	
UPPER HALL		
FLOORING	BIG CARPET SEAM AT UPPER HALL	
BASEMENT		
COLD ROOM	INSPECT/REMOVE STAINS IN COLD ROOM FLOOR	
NOTE:	DUCTS NOT CLEANED	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. & resolute ????? Shankara, Nikhil Rachwani Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Alexandria Damianidis Inspector's Name (print) Designate's Name (print) Designate's Signature Inspector's Signature 2023/08/29 August 29, 2023 Date (YYYY/MM/DD)