

Closing Date: 04Jul23

Address:

Location: Caledon Club - Phase: 1B - Lot: 65B
Today's Date: 12Jun23

Contact(s):
Email:

Company: Newmar

Attention: Alex
Telephone: (905) 672-1233
Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
157936	PDI	EXTERIOR- NOTE:~WINDOW TRIM AT 2 WINDOWS ABOVE FRONT PORCH AND WINDOW. LEFT OF FRONT PORCH FLEW OFF.		
157940	PDI	KITCHEN- WINDOWS~RIGHT SCREEN RIPPED AT SLIDING DOOR.		
157941	PDI	FOYER/HALL- FRONT DOORS~SCRATCH ON RIGHT FIXED DOOR GLASS		
157944	PDI	BEDROOM #3- WINDOWS~ADJUST WINDOW NOT CLOSING.		

Date Completed:

Homeowner Signature:

The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech. _____

Signature: _____

Print Name: _____

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP
7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W182780
Pack Slip:229330
Service Date: Jul 04, 2023

Priority: Normal

Status: SCHEDULED

RELEASED

BUILDER

Customer: N000531
Name: ZANCOR CALEDON CLUB
Service Fax:
Site Fax:

City: CALEDON
Service Phone(s):
Site Phone:
Lot#: 65B

Received: Apr 04, 2023
Time: 1ST CALL
Order: D386576-1
Phase:

RESIDENT INFORMATION

Home Owner Name:
Home Phone(s):
Cell Phone(s):
Address:
Work Phone(s):
Email(s):

LINKED ORDER INFORMATION (D386576-1)

Customer: N000531 ZANCOR CALEDON CLUB
Model: 38-02 WYNDANCE (SL)
Lot #: 65B
Phase:

SERVICE INSTRUCTIONS

SASH WARPED LN#161 CANT CLOSE

ADD:

HORIZONTAL SDL BAR CAME OFF WINDOW ON LINE: 150 (ENS.2), PLEASE REPLACE INTERIOR AND EXTERIOR SDL BAR, PLEASE SCHEDULE FOR MAY 26TH OR JUNE 3RD

ADD:

HORIZONTAL SDL BAR ALSO NEEDS TO BE REPLACED ON LINES: 141, 150 & 161 (FRONT ELEVATION 2ND FLOOR WINDOWS). IT HAS FALLEN OFF.

ADDED ON 06-13-2023:

157936 - EXTERIOR NOTE: WINDOW TRIM AT 2 WINDOWS ABOVE FRONT PORCH AND WINDOW. LEFT OF FRONT PORCH FLEW OFF
157940 - KITCHEN WINDOWS - RIGHT SCREEN RIPPED AT SLIDING DOOR
157941 - FOYER/HALL FRONT DOORS - SCRATCH ON RIGHT FIXED DOOR GLASS
157944 - BEDROOM #3 - WINDOWS - ADJUST WINDOW NOT CLOSING

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
161	NEWMAR VINYL CASEMENT	B2	SASH AND GLASS	22.125 X 66.125	RIGHT SL AG22 LOWE_ARG SIM_SH TOP_ONLY	1
310	NEWMAR VINYL CASEMENT INTERIOR AND EXTERIOR SDL BAR	ENS.2	SDL, SDL-W, SIM DIV, SIM_SH ONLY	24 X 68	AG22 SL SIM_SH	1
451	NEWMAR VINYL CASEMENT	B3	SDL, SDL-W, SIM DIV, SIM_SH ONLY	24 X 68	AG22 SL SIM_SH	1
460	NEWMAR VINYL CASEMENT	ENS.2	SDL, SDL-W, SIM DIV, SIM_SH ONLY	24 X 68	AG22 SL SIM_SH	1
471	NEWMAR VINYL CASEMENT	B2	SDL, SDL-W, SIM DIV, SIM_SH ONLY	24 X 68	AG22 SL SIM_SH	1

Problem Description:

☐ Warranty

Material \$ _____
Labour \$ _____

☐ CHARGEABLES

Material \$ _____
Labour \$ _____
P.O.#: _____

Cause:

Need door insert 22X48 2X2

Solution:

Need Part to door since one L one R

Date Completed:

July 4. 2023

Approved:

Time:

Service Signature:


ZAHER
B