



Priority: Normal Status: SCHEDULED
BUILDER
Customer: N000531
Name: ZANCOR CALEDON CLUB
Service Fax:
Site Fax:
City: CALEDON
Service Phone(s):
Site Phone:
Lot#: 141A
Received: Jul 27, 2023
Time:
Order: D383566-1
Phase:

RESIDENT INFORMATION

Home Owner Name: BHUMIKA MITULKU DESAI & MITULK Address: 148 PETCH AVE.
Home Phone(s): 416-358-1573, 416-357-1573 Work Phone(s):
Cell Phone(s): Email(s): desaibhumika9@gmail.com,
mituldesai9@gmail.com

LINKED ORDER INFORMATION (D383566-1)

Customer: N000531 ZANCOR CALEDON CLUB Lot #: 141A
Model: 38-04 GRANVIEW (RR UPG)/LOT 141A Phase:

SERVICE INSTRUCTIONS

KITCHEN- GENERAL- SLIDING DOOR VERY HARD TO OPEN AND CLOSE → Complete

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

No Builders w/o ATTACHED.

Solution:

Adjusted P.O

Date Completed:

Aug 28/23

Approved:

X B.M. Desai

Time:

35 mins

Service Signature:

RICHARD