

BUILDER:

**Zancor Homes** 

JOB SITE:

Caledon Club

**Customer Code:** 

Job Number:

18338

**Board Area:8** 

COMPLAINT DATE: 06/07/23

LOT:

AMPRICATION OF STREET

65B

INSTALLER:

SCHEDULED DATE: 06/23/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

**ACCESS NOTES:** 

REPAIR TYPE:

PDI

REPAIRMAN:

**BUILDER WO#** 

**BUILDER PO#:** 

PO Required:

NO

Inspection Reqd:

NO

**ORIGINAL WO#:** 

691214

REPAIR DESC:

Adjust carpet shim at entrance to all bathrooms

Master Bedroom - Tuck carpet at left side of window

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

DUE: / 0/

**INSTALLER'S SIGNATURE:** 

SUPER'S/OWNER'S SIGNATURE:

NOTE\*\*\* Please have this memo signed by the owner or site super upon completion.

WARNING






















INSTALLER SIGNATURE







**BUILDER:** 

**Zancor Homes** 

JOB SITE:

Caledon Club

**Customer Code:** 

Job Number:

18338

Board Area:8

COMPLAINT DATE: 06/07/23

LOT:

Without some some Allerti

65B

INSTALLER:

SCHEDULED DATE: 06/23/23

**OWNER NAME:** 

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

**ACCESS NOTES:** 

**REPAIR TYPE:** 

PDI

REPAIRMAN:

**BUILDER WO#** 

**BUILDER PO#:** 

PO Required:

NO

Inspection Regd:

NO

**ORIGINAL WO#:** 

691214

REPAIR DESC:

Adjust carpet shim at entrance to all bathrooms

Master Bedroom - Tuck carpet at left side of window

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

**INSTALLER'S SIGNATURE:** 

NOTE\*\*\* Please have this memo signed by the owner or site super upon completion.

WARNING THINK SAFETY - ALWAYS WEAR YOUR SAFETY SHOES AND HARDHAT



















INSTALLER SIGNATURE

DATE