



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W196678

Pack Slip:237971

Service Date: Sep 12, 2023

Priority: Normal Status: PENDING RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Sep 11, 2023
Name: ZANCOR BELLE AIRE SHORES Service Phone(s):
Service Fax: Site Phone: Time:
Site Fax: Lot#: 353W Order: D392163-1
Phase: 3

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D392163-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 353W
Model: 36-05 GALLEY/SW Phase: 3

SERVICE INSTRUCTIONS

MB OPERATOR GLASS BROKEN

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
81	NEWMAR VINYL CASEMENT	MB	GLASS ONLY - SASH	24.75 X 42.75	CLR LOWE_ARG SW	1

Problem Description:

Complete

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$ 95

Labour \$ 120

P.O.#:

Cause:

Solution: changed glass

Date Completed: Sept 12/23

* Approved: [Signature]

Time:

Service Signature: [Signature]
TONY

Lot 353W

1 message

Carmelo <carmelo@zancorhomes.com>
To: Melissa Green <mgreen@newmar.com>
Cc: Nathan Simas <nathan@zancorhomes.com>

Mon, Sep 11, 2023 at 8:59 AM

406-566-0860

Hi Melissa

As requested here is a picture of the broken window in the master bedroom at lot 353W.



Thank you.
Carm Servello.
Site Supervisor.
Belle Shores Innisfil.
Zancor Homes.
(416)566-0860