

The items listed below were released to the homeowner(s) of

he above items were received on this 21_ day of SEPT, 2022	N/A Other	Homeowner Manual	Lot # 86W Site/Phase: BELLE AIRE SHORES
--	-----------	------------------	---

Outstanding Deficiencies Belle Aire Shores - Phase: 3 - Lot: 86W

20Sep23	20Sep23	20Sep23	<u>20Sep23</u>	20Sep23	20Sep23	<u>26Jun23</u>	<u>26Jun23</u>	26Jun23	<u>Date</u> <u>Reported</u>
PDI	PDI	PDI	PDI	PDI	PDI	Interval	Interval	Interval	Туре
6	5	4	3	13	_	3	2	_	Number
KITCHEN- CABINETS-OVER SPRAY INSIDE CABINETS AT GABLES FRONT FRONT CABINETS.	KITCHEN- CABINETS-CHIP INSIDE BOTTOM GABLE LEFT OF FRIDGE.	DINING ROOM- FLOORING-CUT OUT FOR HRV UNIT TOO SMALL	FOYER/HALL- STAIRS~SCRATCH ON NEWEL AND NOSING AT 2ND FLOOR SIDE BY SIDE.	MASTER ENSUITE BATH- VANITY CABINETS~CHIP AT BOTTOM GABLE BELOW RIGHT SINK.	BEDROOM #4- WINDOWS~ADJUST WINDOW HARD TO OPEN	Exterior- General- rear light not centered with anything	Exterior- General- caulk service/gasline	Exterior- General- flashing above porch	Deficiency Description
New Image Kitchens 163100	New Image Kitchens 163099	First Canadian Hardwood 163098	Bolton Railings Inc. 163097	New Image Kitchens 163096	Newmar 163095	Dart Electric 158436	CJ Caulking 158435	Trudel & Sons Roofing LTD. 158434	<u>Trade</u> <u>Assigned</u>
Add	<u>Add</u>	Add	Add	Add	Add	Add	Add	Add	Add Trade
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	Add Appointment Trade Date
									Item Completed
								NX	Initial

Date:Zancor Service Technician:	The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.	Homeowner Signature: