Enrollment:

Purchaser Name:

Thanh, Trung Nguyen

Phone Res:

Phone Bus: (647) 830-5737 Closing Date: September 28, 2023 HOMES

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 361W / 3

Plan: Address:

Inspection Date: September 22, 2023

Municiaplity: Inspector: Alexandria Damianidis Page 1 of 2

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH		
FAUCETS/PLUMBING	STANDARD BATH ACCESSORIES NOT SUPPLIED THROUGHOUT - SITE TO INSTAL BASED ON	
	PHOTOS FOR LOCATIONS	
FLOORING	GROUT REQUIRED IN SHOWER THROUGHOUT	
NOTE:	WINDOW SCREEN NOT INSTALLED	
UPPER HALL		
FLOORING	REMOVE MUD STAINS ON CARPET AT UPPER HALL BELOW SMOKE ALARM	
BEDROOM #2		
FLOORING	REMOVE MUD, STAINS ON CARPET BELOLOW LIGHT FIXTURE	
WALK IN CLOSET	CUT AND TUCK CARPET IN CLOSET	
KITCHEN		
CABINETS	REMOVE PLASTIC PROTECTOR ON KITCHEN CABINETS THROUGHOUT	
	CHIPS ON BOTTOM GABLE BELOW AT FRIDGE CUT OUT AND FILLER PIECE BESIDE RIGHT SIDE	
	INSPECT SCRATCH ON CABINET BELOW SINK RIGHT SIDE	
	CHIP AT ISLAND ON RIGHT SIDE IN FRONT OF STOVE CUT OUT	
FLOORING	OVERCUT AT TILE ON LEFT-HAND SIDE AT SLIDING DOOR	
MASTER BEDROOM		
FLOORING	INSPECT FLOOR SQUEAK LEFT HEAT REGISTER BELOW WINDOW	
FOYER/HALL		
STAIRS	WATER DAMAGE AT 6TH TREAD AND INSIDE STRINGER AT STAIRS TO 2ND FLOOR	
	WATER DAMAGE AT OUTSIDE, STRINGER AT MAIN STAIRS	
TRIM	INSPECT GAP AT DOORWAY, TRIM ON RIGHT SIDE PAST POWDER ROOM. BIG GAP IN BETWEEN	
	HARDWOOD AND TRIM. HOMEOWNER REQUESTING TO HAVE THIS REPLACED OR FILLED.	
FRONT DOORS	CHIPS AT MIDDLE ASTRICAL AT FRONT DOOR	
FLOORING	TOUCHUP GROUT A TILE AND NOSING AT FOYER AT SECOND LANDING	
CLOSET	REPLACE LEFT CLOSET DOOR HANDLE AT MUD ROOM SCRATCHED	

Enrollment: Purchaser Name: ????

Thanh, Trung Nguyen

Phone Res:

Phone Bus: (647) 830-5737

Closing Date: September 28, 2023
Inspector: Alexandria Damianidis



Page 2 of 2

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 361W / 3

Plan: Address:

Municiaplity:

Inspection Date: September 22, 2023

REMOVE PLASTER FROM GARAGE FLOOR SLAB

A REFERENCE FOR FUTURE WAR	RANTY REQUESTS. to designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHASS their place should ensure they provide written auth	
I have inspected my new home and	I agree that the description of the items listed	on this form are accurate.	
????	10m/m	Thanh, Trung Nguyen	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Alexandria Damianidis	
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/09/22	September 22, 2023	