Enrollment:

Phone Res:

Purchaser Name: ??????

Vimmi Kohly

Phone Bus: (416) 471-9394

Closing Date: September 28, 2023

Inspector: Gisella Fiore Page 1 of 2

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 151 Unit 1 / 1

Plan: Address: Municiaplity:

Inspection Date: September 27, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN			
FLOORING	OVER CUT AT REGISTER RIGHT OF SLIDING DOOR		
CABINETS	CHIP AT LEFT GABLE LEFT OF SINK AT FLOOR LINE.		
	UPPER CABINET AND LEFT OF SINK TOP PANEL EDGE PEELING		
WINDOWS	RIPPED SLIDING DOOR SCREEN		
COUNTERTOPS	HOMEOWNERS UNHAPPY WITH SEAM IN BETWEEN COUNTERTOP AT EDGE RIGHT OF STOVE.		
	ONE SIDE ROUGH OTHER SMOOTH.		
	CHIPPED COUNTERTOP LEFT OF STOVE BY DRYWALL.		
POWDER ROOM		,	
FLOORING	CHIP AT 1ST TILE INFRONT OF TOLIET.		
FOYER/HALL			
STAIRS	RAISED NOSING RIGHT OF STAIRS AT TILES.		
	CHIP ON 3,4 RISER AT STAIRS FROM MAIN TO 3RD FLOOR.		
	CHIP AND EXPOSED SCREWS BELOW NOSING AT MAIN FLOOR STAIRS TO 1ST FLOOR.		
	CHIPS ON OUTSIDE STRINGER WHERE MEETS POST BELOW NOSING AT LANDING TOO 3RD		
	FLOOR AND POST.		
	HOLE IN OUTSIDE STRINGER AT CEILING AT 2ND FLOOR.		
	CRACK ON 2ND TREAD AT STAIRS FROM LANDING TO 3RD FLOOR.		
	CHIP ON HARDWOOD PLANK BY NOSING AT 2ND FLOOR		
	CHIP ON POST LEFT OF TREAD AT 1ST LANDING FROM FIRST FLOOR TOO 2ND FLOOR.		
	DENT ON NEWEL AT LANDING TO 2ND FLOOR.		
	HOLES ON RAILING AT STAIRS FROM 1ST TOO 2ND FLOOR.		
	STAIN REQUIRED BELOW RISER AT FIRST FLOOR		
UPPER HALL			
FLOORING	LARGE CHIP ON 3RD PLANK FROM NOSING AT 3RD FLOOR HALLWAY		

Enrollment: Purchaser Name: ??????

Phone Res:

Vimmi Kohly

Closing Date: September 28, 2023

Inspector: Gisella Fiore

Phone Bus: (416) 471-9394



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 151 Unit 1 / 1

Plan: Address: Municiaplity:

Page 2 of 2 Inspection Date: September 27, 2023

MACTER REPROCES		
MASTER BEDROOM		
FLOORING	INSPECT RAISED HARDWOOD PLANK BELOW DOOR TO MASER BEDROOM WALK IN.	
BEDROOM #2		
FLOORING	SMALL CHIP ON 9TH HARDWOOD PLANK FROM RIGHT WALL.	
EXTERIOR		
PAINT	TOUCH UP OPERATING DOOR RIGHT SIDE CHIPPED	
NOTE:	SCRATCHES ON EXTERIOR AND ASTRICAL AT FRONT DOOR	
GARAGE DOORS	DENTS ON GARAGE DOOR INTERIOR FOAM	
	CHIPS ON GARAGE DOOR - PAINT REQUIRED	
	DAMAGE AT GARAGE TRIM	

A REFERENCE FOR FUTURE WARRA	NTY REQUESTS. designate someone to conduct the PDI in th	HOME'S CONDITION BEFORE THE PURCHASE eir place should ensure they provide written authors.	
I have inspected my new home and I a	agree that the description of the items listed	on this form are accurate.	
??????	XX	Vimmi Kohly	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Gisella Fiore	
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/09/27	September 27, 2023	