



Zancor Homes (Cookstown) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 25Feb21

Address:

Location: Cookstown - Phase: 1 - Lot: 35

Today's Date: 05Apr23

Contact(s): 2ND HOME OWNER Rogini Thirukkumaran - Cell: (647) 968-9771 -
(rogini144@gmail.com)

Email: rogini144@gmail.com


Company: Medi Group

Attention:

Telephone: (416) 741-2737

Fax: (416) 741-1593

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
155894	2 Year	Exterior- General- Some of the exterior Window sills have a through cracks (the White Stones) - Bedroom 2 - Dining Room Window - Family Room Window 1, 2 ,		 09/22/23

Date Completed: _____

Homeowner Signature: _____

The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech.

Signature: _____

Print Name: _____

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and



MEDI GROUP Service

WO Number : **W-089103**WO Date : **19-Sep-2023**Issued To : **ROBERT ULJASZ**Builder : **Zancor****ZAN08**Project : **ZANCOR HOMES (COOKSTOWN) LTD.**Lot No : **35**Model : **6002 (B)**Directions : **Cookstown**Intersection of Queen St (Hwy 89) and
Dufferin St (south of Queen and west ofAddress : **28 Victoria Street**Contact : C x 2Main Brick : **Old School**

Main Stone :

Accent Brick :

Accent Stone : **Ryegrass Renaissance**

INIT

Item

Work Description

PO

Builder Ref #

1

**SOME OF THE EXTERIOR WINDOW SILLS HAVE A THROUGH
CRACKS - SEE PHOTOS**

35APR0623

S-067651

Replace 4 sills.
Repair 3 sills

20 Sept/23

Scheduled
09
20

Homeowner Signature

Date Completed

Site Super Signature

Date Completed

Special Notes :

COMPLETED
COMPLETED SEP 22 2023

Cookstown - Phase: 1 - Lot: 35

155894 - 1 - 20230327_183918 - Some of the exterior Window sills have a through cracks (the White Stones) - Bedroom 2 - Dining Room Window - Family Room Window 1, 2 ,



155894 - 2 - 20230319_182941 - Some of the exterior Window sills have a through cracks (the White Stones) - Bedroom 2 - Dining Room Window - Family Room Window 1, 2 ,



155894 - 3 - 20230319_182831 - Some of the exterior Window sills have a through cracks (the White Stones) - Bedroom 2 - Dining Room Window - Family Room Window 1, 2 ,



155894 - 4 - 20230319_182815 - Some of the exterior Window sills have a through cracks (the White Stones) - Bedroom 2 - Dining Room Window - Family Room Window 1, 2 ,



155894 - 5 - 20230319_183048 - Some of the exterior Window sills have a through cracks (the White Stones) - Bedroom 2 - Dining Room Window - Family Room Window 1, 2 ,

155894 - 6 - 20230319_183406 - Some of the exterior Window sills have a through cracks (the White Stones) - Bedroom 2 - Dining Room Window - Family Room Window 1, 2 ,

