

**ZANCOR**  
HOMES  
Zancor Homes (Caledon) Ltd.  
Warranty Services  
Phone: (905) 738-7010  
Fax: (905) 738-5948

Work Order

Closing Date: 18Aug22

Address:

Location: Caledon Club - Phase: 1 - Lot: 107A

Today's Date: 21Sep23

Contact(s): Fraz Tabassam - Work: (647) 210-0667 - (fraztabassam@gmail.com)

iqra Shahid - Work: (647) 293-5669 - (iqrafraz24@gmail.com)

Email: fraztabassam@gmail.com

Company: Promark Aluminum LTD.

Attention: Kamar Kuyumju - Cell: 416-576-0236

Telephone: (905) 857-5692

Fax: (905) 857-5961

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
151033	30-Day	Exterior- General- Item #19 metal flashing missing on left side of house by powder room window at lentil	14Oct22 /pm	- Not Promark we do not cover lentil
151413	Interval	Exterior- General- damage downspout left side of house due to scaffold	o/s	
161942	1 Year	Exterior- General- Front left side window iron lentil was exposed, and its cover was observed damaged		* we do not cover lentil. Promark

Date Completed:

Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed:

Trade &/or Service Tech.

Signature:

**Caledon Club - Phase: 1 - Lot: 107A**

**151413 - 1 - 4 - damage downspout left side of house due to scaffold**



**151413 - 2 - 2 - damage downspout left side of house due to scaffold**

