Enrollment:

Purchaser Name: Andrew Austin SMITH

Phone Res: (905) 462-0015

Phone Bus:

Closing Date: October 32, 2023

Inspector: Alexandria Damianidis

HOMES

Project: Zancor Oakville Ltd.

Lot / Phase: 513 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 513

Municiaplity:

Vendor / Builder:

Inspection Date: October 05, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
CABINETS	CHIP AT UPPER CORNER ABOVE DISHWASHER	
	CHIPS AT FILLER PIECE LEFT OF FRIDGE	
	CHIPS AT KICKPLATE BELOW FREEZER	
	CHIPS AT FILLER, PLEASE LEFT OF BANK OF DRAWERS AT FLOONLINE	
	ADJUST LOWER CABINET LEFT OF STOVE	
	CHIPS AT BOTTOM GABLE BELOW SINK	
	CHIP AT UPPER CABINET ABOVE FRIDGE	
SINK/FAUCET/PLUMBING	FRIDGE AND FREEZER NOT ON	
ELECTRICAL/LIGHTING	STOVE NOT TURNING ON	
WINDOWS	SLIDING DOOR, HARD TO OPEN AND CLOSE	 - <u></u>
FOYER/HALL		
NOTE:	REMOVE PAINT FROM ROGERS BOX	
	YEAHDIRT/SCRATCHES ON MIRROR	
POWDER ROOM		
SINK/FAUCET/PLUMBING	OVERCUT, PLUMBING WALL TILE	
TRIM	DOORSTOP NOT INSTALLED	 - <u></u>
MASTER BEDROOM		
WALK IN CLOSET	MARKS ON CLOSET MIRROR	

Enrollment:

Purchaser Name: Andrew Austin SMITH

Phone Res: (905) 462-0015

Phone Bus:

Designate's Name (print)

Date (YYYY/MM/DD)

Closing Date: October 32, 2023

Inspector: Alexandria Damianidis

ZANCOR

Page 2 of 2

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 513 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 513

Inspector's Signature

Municiaplity:

Inspection Date: October 05, 2023

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Andrew Austin SMITH

Purchaser's Name (print)

Purchaser's Signature

Alexandria Damianidis

Inspector's Name (print)

October 05, 2023

Designate's Signature

2023/10/05