



Quality Sterling Group

Mike

REPAIR ORDER
748258



NC

BUILDER: Zancor Homes JOB SITE: Caledon Club
Customer Code: Job Number: 18338 Board Area: 8
COMPLAINT DATE: 09/14/23 LOT: 107B
INSTALLER: SCHEDULED DATE: 10/06/23
OWNER NAME: OWNER TEL:
OWNER ADDR: REPAIR DURATION: 0
ACCESS NOTES: REPAIR TYPE:
REPAIRMAN: BUILDER WO#
BUILDER PO#: PO Required: NO Inspection Req'd: NO
ORIGINAL WO#: 704519
REPAIR DESC: Tuck carpet at tile transition at main bathroom
PROD INFO/NOTES: SUPPLIER: PO#: DUE: / /
PROD ORDERED: SUPPLIER: PO#: DUE: / /

INSTALLER'S SIGNATURE: _____

SUPER'S/OWNER'S SIGNATURE: _____

DATE: _____

NOTE*** Please have this memo signed by the owner or site super upon completion.

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

INSTALLER SIGNATURE DATE

