


Enrollment: Purchaser Name: Venkata Rammohan YARLAGADDA Phone Res: (416) 906-4480 Phone Bus: Closing Date: October 32, 2023 Inspector: Gisella Fiore		Vendor / Builder: Project: Zancor Oakville Ltd. Lot / Phase: 510 / 1 Plan: Address: 2450 Old Bronte Road, Suite 510 Municipality: Inspection Date: October 16, 2023
Page 1 of 2		

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl. circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN			
CABINETS	REMOVE FILM OFF EDGES OF CABINETS.	_____	_____
	CHIP AT BOTTOM GABLE BELOW SINK.	_____	_____
MASTER ENSUITE BATH			
VANITY CABINETS	CHIP INSIDE BOTTOM CABINET BELOW SINK AT GABLE.	_____	_____
MAIN BATHROOM			
VANITY CABINETS	CHIP AT BOTTOM GABLE BELOW SINK.	_____	_____
TRIM	MISSING DOOR STOP BEHIND DOOR.	_____	_____
LAUNDRY ROOM			
NOTE:	TILE BASEBOARD NOT INSTALLED LEFT OF DOOR.	_____	_____

Enrollment:
Purchaser Name: Venkata Rammohan YARLAGADDA
Phone Res: (416) 906-4480
Phone Bus:
Closing Date: October 32, 2023
Inspector: Gisella Fiore



Page 2 of 2

Vendor / Builder:
Project: Zancor Oakville Ltd.
Lot / Phase: 510 / 1
Plan:
Address: 2450 Old Bronte Road, Suite 510
Municipality:
Inspection Date: October 16, 2023

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

** Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.*

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Venkata Rammohan YARLAGADDA

Purchaser's Name (print)

Purchaser's Signature

A handwritten signature in black ink, appearing to be "Venkata Rammohan YARLAGADDA".

Purchaser's Name (print)

Purchaser's Signature

A handwritten signature in black ink, appearing to be "Gisella Fiore".

Gisella Fiore

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD)

2023/10/16

October 16, 2023