Enrollment:

Purchaser Name: Arun Thoma ALEX

Alexander THOMAS

Phone Res: (416) 305-6110 Phone Bus: (416) 305-6110 Closing Date: October 31, 2023

Inspector: Gisella Fiore

HOMES

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 503 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 503

Municiaplity:

Inspection Date: October 20, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

CABINETS ADJUST DW HARD TO OPEN SHELF NOT INSTALLED A T RIGHT LOWER CABINET. CHIP AFT UPPER GABLE ABOVE FRIDGE. FLOORING SCRATCH ON FIRST VINYL PLANK INFRONT OF STOVE  MAIN BATHROOM  VANITY CABINETS CHIP AT BOTTOM GABLE BELOW SINK AND RIGHT GABLE. AND LEFT GABLE ADJUST CABINET AND DRAWER NOT STRAIGHT.  BEDROOM #2  TRIM RAISED TRIM AT CLOSET DOOR RIGHT AND LEFT SIDE.  LIVING ROOM  NOTE: FURNACE NOT CONNECTED WINDOWS ADJUST SLIDING AND SCREEN DOOR	
CHIP AFT UPPER GABLE ABOVE FRIDGE.  FLOORING SCRATCH ON FIRST VINYL PLANK INFRONT OF STOVE  MAIN BATHROOM  VANITY CABINETS CHIP AT BOTTOM GABLE BELOW SINK AND RIGHT GABLE. AND LEFT GABLE ADJUST CABINET AND DRAWER NOT STRAIGHT.  BEDROOM #2  TRIM RAISED TRIM AT CLOSET DOOR RIGHT AND LEFT SIDE.  LIVING ROOM  NOTE: FURNACE NOT CONNECTED	
FLOORING SCRATCH ON FIRST VINYL PLANK INFRONT OF STOVE  MAIN BATHROOM  VANITY CABINETS CHIP AT BOTTOM GABLE BELOW SINK AND RIGHT GABLE. AND LEFT GABLE ADJUST CABINET AND DRAWER NOT STRAIGHT.  BEDROOM #2  TRIM RAISED TRIM AT CLOSET DOOR RIGHT AND LEFT SIDE.  LIVING ROOM  NOTE: FURNACE NOT CONNECTED	
MAIN BATHROOM  VANITY CABINETS  CHIP AT BOTTOM GABLE BELOW SINK AND RIGHT GABLE. AND LEFT GABLE ADJUST CABINET AND DRAWER NOT STRAIGHT.  BEDROOM #2  TRIM RAISED TRIM AT CLOSET DOOR RIGHT AND LEFT SIDE.  LIVING ROOM  NOTE: FURNACE NOT CONNECTED	
VANITY CABINETS  CHIP AT BOTTOM GABLE BELOW SINK AND RIGHT GABLE. AND LEFT GABLE ADJUST CABINET AND DRAWER NOT STRAIGHT.  BEDROOM #2  TRIM RAISED TRIM AT CLOSET DOOR RIGHT AND LEFT SIDE.  LIVING ROOM  NOTE: FURNACE NOT CONNECTED	
ADJUST CABINET AND DRAWER NOT STRAIGHT.  BEDROOM #2  TRIM RAISED TRIM AT CLOSET DOOR RIGHT AND LEFT SIDE.  LIVING ROOM  NOTE: FURNACE NOT CONNECTED	
BEDROOM #2  TRIM RAISED TRIM AT CLOSET DOOR RIGHT AND LEFT SIDE.  LIVING ROOM  NOTE: FURNACE NOT CONNECTED	
TRIM RAISED TRIM AT CLOSET DOOR RIGHT AND LEFT SIDE.  LIVING ROOM  NOTE: FURNACE NOT CONNECTED	
LIVING ROOM  NOTE: FURNACE NOT CONNECTED	
NOTE: FURNACE NOT CONNECTED	
WINDOWS AD HIST SHIPING AND SCREEN DOOR	
WINDOWS ADJUST SCIDING AND SCREEN DOOR	
MASTER BEDROOM	
FLOORING OVERCUT AT VINYL LEFT, SIDED ENTRANCE TO BEDROOM	
WINDOWS ADJUST WINDOW, CRANK, NOT CLOSING	
ADJUST WINDOW TRIM ABOVE OPERATING WINDOW SLANTED.	
MASTER ENSUITE BATH	
NOTE: REMOVE SILICONE OFF GLASS SHOWER AT FIXED PANEL	
FLOORING ADJUST TRIM RIGHT OF DOOR TILE ON ANGLE	
VANITY CABINETS CHIP AT ALL BOTTOM GABLES BELOW SINK.	
SHOWER ENCLOSURE GLASS DOOR MOVING WHEN PUSHED ON SECURE GLASS.	

**Enrollment:** 

Purchaser Name: Arun Thoma ALEX

Alexander THOMAS

Phone Res: (416) 305-6110 Phone Bus: (416) 305-6110 Closing Date: October 31, 2023 Inspector: Gisella Fiore

ZANCOR

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 503 / 1 Plan:

Address: 2450 Old Bronte Road, Suite 503

Municiaplity:

Inspection Date: October 20, 2023

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

\* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Arun Thoma ALEX Alexander THOMAS Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Gisella Fiore Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature Date (YYYY/MM/DD) 2023/10/20 October 20, 2023