Enrollment:

Purchaser Name: Lilly SVIRKSTS

Phone Res: (416) 725-4772

Phone Bus:

Closing Date: November 07, 2023

Inspector: Gisella Fiore Page 1 of 2

HOMES

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 706 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 706

Municiaplity:

Inspection Date: October 23, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
CABINETS	CHIP AT BOTTOM GABLE BELOW FREEZER AT EDGE.	
	CHIP AT TOP SHELF LEFT OF FRIDGE.	
	CHIP AT UPPER LEFT CABINET LEFT OF MICROWAVE AND CABINET ABOVE MICROWAVE LEFT	
	SIDE AND ADJUST CABINET RUBBING.	
	DAMAGED BOTTOM GABLE ABOVE SINK.	
	SECURE KICKPLATE BELOW SINK AND SMALL CHIP.	
	UNFINISHED STRIP EDGE BELOW UPPER CABINET ABOVE SINK	
NOTE:	REMOVE STAINS OFF DRAIN AND LEFT SIDE IN SINK.	
	INSPECT GREY. SEAL LEFT SIDE INSIDE STOVE NOT SECURED.	
	SECURE ACCESS PANEL LOOSE INSIDE CLOSET	
MASTER BEDROOM		
TRIM	HOMEOWNER REQUESTING TO HAVE DOOR CHANGED. DUE TO CRACK - NOT ACCEPTING	
	REPAIR.	
WINDOWS	SCRATCH ON MULIN ABOVE OPERATING WINDOW	
NOTE:	SCRATCH ON SLIDING MIRROR.	
	SCRATCH ON ELECTRICAL PANEL	
LAUNDRY ROOM		
SINK/FAUCET/PLUMBING	SECURE WATER SHUT OFF LEFT OF WASHER.	
MAIN BATHROOM		
VANITY CABINETS	CHIP ON LEFT CABINET GABLE BY DRYWALL.	
	UPGRADED BLACK BATHROOM ACCESSORIES NOT INSTALLED SEE LOCATION.	
	CHIP INSIDE BOTTOM GABLE BELOW SINK AND LEFT CABINET	
	LIGHT FIXTURE NOT STRAIGHT.	
NOTE:	SCRATCH ON TOP HINGE AT SHOWER.	

Enrollment:

Purchaser Name: Lilly SVIRKSTS

Phone Res: (416) 725-4772

Phone Bus:

Date (YYYY/MM/DD)

2023/10/23

Closing Date: November 07, 2023

Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 706 / 1 Plan:

Address: 2450 Old Bronte Road, Suite 706

Municiaplity:

Inspection Date: October 23, 2023

LIVING ROOM			
WINDOWS	SCRATCH ON LEFT TRIM AND TRIM. SHORT ABOVE SLIDING DOOR LEFT SIDE.		
-	MISSING FURNACE FILTERS		

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. L. Si Wre Lilly SVIRKSTS Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Gisella Fiore Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature

October 23, 2023