

R	ш	1	F	R	٠

**Zancor Homes** 

JOB SITE:

River's Edge

**Customer Code:** 

Job Number:

18646 Board Area:18

COMPLAINT DATE: 09/25/23

LOT:

INSTALLER:

330

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

SCHEDULED DATE: 10/13/23

**ACCESS NOTES:** 

REPAIR TYPE:

PDI

REPAIRMAN:

**BUILDER WO#** 

Inspection Reqd:

NO

**BUILDER PO#:** 

PO Required:

NO

**ORIGINAL WO#:** 

742179

REPAIR DESC:

Raise carpet at all bathroom thresholds

Bedroom 4 - Pull carpet at centre of room

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

**INSTALLER'S SIGNATURE:** 

SUPER'S/OWNER'S SIGNATURE:

NOTE\*\*\* Please have this memo signed by the owner or site super upon completion.

WARNING THINK SAFETY - ALWAYS WEAR YOUR SAFETY SHOES AND HARDHAT




















INSTALLER SIGNATURE

DATE



Mike



**BUILDER:** 

**Zancor Homes** 

JOB SITE:

River's Edge

**Customer Code:** 

Job Number:

18646 Board Area:18

COMPLAINT DATE: 09/25/23

LOT:

330

INSTALLER:

SCHEDULED DATE: 10/13/23

OWNER TEL:

REPAIR DURATION: 0

**ACCESS NOTES:** 

OWNER NAME:

OWNER ADDR:

REPAIR TYPE: **BUILDER WO#**  PDI

REPAIRMAN:

NO

Inspection Regd:

NO

**BUILDER PO#:** 

PO Required:

**ORIGINAL WO#:** 

742179

REPAIR DESC:

Raise carpet at all bathroom thresholds

Bedroom 4 - Pull carpet at centre of room

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

Did not inspect

PO#:

DUE: / 0/

**INSTALLER'S SIGNATURE:** 

SUPER'S/OWNER'S SIGNATURE:

DATE: 13t10ct 2023

NOTE\*\*\* Please have this memo signed by the owner or site super upon completion.

WARNING THINK SAFETY - ALWAYS WEAR YOUR SAFETY SHOES AND HARDHAT



















INSTALLER SIGNATURE

DATE