

Zancor Homes (Caledon) Ltd.

**Warranty Services** 

Phone: (905) 738-7010 Fax: (905) 738-5948

**Work Order** 

Closing Date: 14Sep23

Address:

Location: Caledon Club - Phase: 1B - Lot: 50B

Today's Date: 260ct23

Contact(s): Mary Kiujin R Anton Rajkumar - Cell: (416) 569-0588 - (jenush2@hotmail.com)

jenush2@hotmail.com

Company: Zancor -Caledon

Attention:

Telephone:

Fax:

Please Complete the following items:

DAI	Туре	Issue		Appt. Date/Time	Notes
165061	Interval	Other- General- SVC TO DRYWALL AT BLANK COVER PLATE	7	260ct23 /am	
165063	Interval	Other- General- SVC REMOVE BLACK FILM OFF WINDOW	74	26Oct23 /am	
165065	Interval	Other- General- SVC TO REPAIR DOOR JAMB AS COUTESY	712	/260ct23 /am	

Date Completed: Y

Homeowner Signature:

has been completed in a workman like manner. The Homeowner acknowledges and accepts all work

Date Completed:

Signature:

Trade &/or Service Tech.

Print Name:

adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no

Work Order

Closing Date: 10Aug23
Address:
Location: Belle Aire Sh
Today's Date: 16Oct23
Contact(s): Manish Singh

Belle Aire Shores - Phase: 3 - Lot: 305W
16Oct23
Manish Singh Arora - Cell: (647) 972-6980 - (manish.arora@outlook.in)
Anshu Gadnok - Cell: (647) 920-6864 - (anshu.gadhok@outlook.com)
manish.arora@outlook.in

Email:

Zancor - Innisfil Warranty Service

Attention: Telephone: Fax:

Please Complete the following items:

DAI	Type	SSUE		Appt. Date/Time	Notes
163895	30-Day	Exterior- General- 6 EXTERIOR Lot/Property/Yard Yard - Side Air Conditioning/Cooling Source Wire mesh missing from in and out pipes -LOCK BOX is 2790. The lockbox is located on porch right- side railing.		25Oct23 /am	lock box 2790
163896	30-Day	Study- General- 7 INTERIOR Floor 01 Den/Study Windows Need Fnishing image.jpg Window in office room need finishingsvvc caulk image.jpg Need paint finis	1	250ct23 /am	lock box 2790
163898	зо-Дау	Exterior- General- 9 EXTERIOR Roof (Exterior) Building Face/Exterior Foundation (Footings,		250ct23 /am	lock box 2790

163913	163912	163910	163909	163908	163903	163902	
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	
Main Hall- General- 23 INTERIOR Floor 01 Hallway Wall Not square wall at	Main Hall- General- 23 INTERIOR Floor 01 Hallway Wall Not square wall at entrance left	Stairs- General- 21 INTERIOR Floor 01 Stairs Other (Please describe) Title not aligned with stairs	Basement- General- 20 INTERIOR Basement Stairs Staircase/Steps Squeaky staircase and landing	Main Bathroom- General- 19 INTERIOR Floor 01 Bathroom Doors Powder room door need finishing touch	Exterior- General- 14 EXTERIOR Lot/Property/Yard Yard - Front Walkway There was no walkway in site plan provided in Agreement of Purchase And Sell, but its present at the propertyNA	Exterior- General- 13 EXTERIOR Lot/Property/Yard Yard - Side Other (Please describe) Drain pipe cover - sump pump	etc.) Crack
					1	1	
25Oct23 /am	25Oct23 /am	25Oct23 /am	25Oct23 /am	250ct23 /am	250ct23 /am	250ct23	
lock box 2790	OCK POX 5280	lock box 2790	OF THE INSPEC	lock box 2790	lock box 2790	lock box 2790	

163926	163924	163923	163922	163921	163920	163918	163917	163916	163915
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day
Study- General- 38 INTERIOR Floor 01	Bedroom 2- General- 36 INTERIOR Floor 02 Bedroom Windows Caulking sealant	Laundry Room- General- 35 INTERIOR Floor 01 Laundry Room Floor Tile need finishing	Bedroom 2- General- 33 INTERIOR Floor 02 Bedroom Windows Bedroom window need finishing	Bedroom 2- General- 32 INTERIOR Floor 02 Bedroom Windows Caulking sealant	Bedroom 4- General- 31 INTERIOR Floor 02 Bedroom Doors Bedroom closel door need finishing	Loft Bedroom- General- 29 INTERIOR Floor 02 Bathroom Windows Caulking sealant	Stairs- General- 28 INTERIOR Floor 01 Stairs Staircase/Steps Squeaky stairs and landing	Main Hall- General- 27 INTERIOR Floor 01 Hallway Wall Dent and holes in stairs wall	Laundry Room- General- 26 INTERIOR Floor 02 Laundry Room Wall Nail hole on the wall
	T		1	7	1	1	M	7	<
250ct23 /am	250 ct23 /am	25Oct23 /am	250ct23 /am	/50ct23 /am	250ct23	250 ct23	/am	25Oct23 /am	250ct23 /am
lock box 2790	lock box 2790	lock box 2790	lock box 2790	lock box 2790	lock box 2790	lock box 2790	lock box 2790	lock box 2790	lock box 2790

163936	163935	163934	163933	163932	163930	163929	163928	
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	
Main Hall- General- 51 INTERIOR Floor 01 Hallway Floor Flooring	Stairs- General- 50 INTERIOR Basement Stairs Other (Please describe) Holes in wall -NA UNFINISHED AREA	Bedroom 3- General- 46 INTERIOR Floor 02 Bedroom Closet Finishing	Kitchen- General- 45 INTERIOR Floor 01 Kitchen Other (Please describe) Window in kitchen area need finishing. Caulking missing around edges	Main Bathroom- General- 44 INTERIOR Floor 02 Bathroom Windows Caulking sealant	Great Room- General- 42 INTERIOR Floor 01 Great/Grand/Family Room Other (Please describe) Window in family room need finishing	Main Bathroom- General- 41 INTERIOR Floor 02 Bathroom Windows Caulking sealant	Living Room- General- 40 INTERIOR Floor 01 Living Room Windows Window need finishing	Den/Study Windows Window need finishing. Cocking missing on edges
	<		-	1		7	7	
250ct23 /am	250ct23	25Oct23 /am	250ct23 /am	350ct23 /am	250ct23	25Oct23 am	750ct23 /am	
lock box 2790	lack box 2790	lock box 2790	lock box 2790	lack box 2790	lock box 2790	lock box 2790	lock box 2790	

	163938	163939	163940	163960	164389
	30-Дау	30-Day	30-Day	30-Day	Interval
52 INTERIOR Basement Unfinished Area Other (Please describe) Cracks on floor - SVC MEASURE	Other- General- 53 INTERIOR Basement Unfinished Area Other (Please describe) Studs no properly installed	Other- General- 54 INTERIOR Basement Unfinished Area Ventilation Not sealed properly image.jpg Not sealed properly - SVC INSPECT	Basement- General- 55 INTERIOR Basement Unfinished Area Ceiling Duct work not properly done - SVC INSPECT	Laundry Room- General- ITEM #34 NEED FINISHING - SVC CAULK AT TRIM TILE	Powder Room- General- remove jamb at powder room for tile replacement with AV
<			1		
am a	250ct23 /am	25Oct23 /am	250ct23 /am	250ct23 /am	25Oct23 /am
BHU SETT	lock box 2790	lock bax 2790	lock box 2790	lock box 2790	lock box 2790
inished fam	describe) Cracks on floor - SVC MEASURE	describe) Cracks on floor - SVC MEASURE  30-Day Other- General- 53 25Oct23   NTERIOR Basement Unfinished Area Other (Please describe)   Studs no properly installed	describe) Cracks on floor - SVC MEASURE  30-Day Other- General- 53 25Oct23 INTERIOR Basement Unfinished Area Other (Please describe) Studs no properly installed  30-Day Other- General- 54 INTERIOR Basement Unfinished Area Ventilation Not sealed properly image.jpg Not sealed properly - SVC INSPECT	describe) Cracks on floor - SVC MEASURE  30-Day Other- General- 53	describe) Cracks on floor - SVC MEASURE  Other- General- 53 INTERIOR Basement Unfinished Area Other (Please describe) Studs no properly installed  Other- General- 54 INTERIOR Basement Unfinished Area Ventilation Not sealed properly image.jpg Not sealed pro image.jpg Not sealed properly - SVC INSPECT  Basement- General- 55 INTERIOR Basement Unfinished Area Ceiling Duct work not properly done - SVC INSPECT  Laundry Room- General- ITEM #34 NEED FINISHING - SVC CAULK AT TRIM TILE

Date Completed:

Date Completed: Rt 25/23

Homeowner Signature:
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Trade &/or Service Tech.

Signature Recorded M

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4387.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

ZANCOR Zancor Homes (Caledon) Ltd.

HOMES Phone: (905) 738-7010

Fax: (905) 738-5948

Closing Date: 02Aug28
Address: Caledon Glu
Location: 17Oct23
Contact(s): Vilaksh Bans

Caledon Club - Phase: 1B - Lot: 8B
170ct23
Vilaksh Bansal - Cell: (437) 230-2806 - (vilaksh89@gmail.com)
Yogita Bansal - Cell: (416) 417-3836 - (yobansal.44@gmail.com)
vilaksh89@gmail.com

Email:

Zancor -Caledon

Company Attention: Telephone: Fax:

Please Complete the following items:

Other- General- Main Bathroom- General- silicon filling on bath tub tap Other- General- Gap within gates and wall filling with dap- showed to Roman he sald he can take care Other- General- Paint on roof and wall where leakage happened Foyer- General- touch power Upper Hall- General- touch up door trim at upper hall
260ct23 am 260ct23 am 260ct23 am 260ct23 am 260ct23

Date Completed Uct 26

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

KOCHMEN

page 1 / 2

Date Completed: Oct 26/23

Trade &/or Service Tech:

Print Name:

Signatur

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4387.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Closing Date: 11Aug23
Address: Caledon Club
Location: Gloci23
Today's Date: 16Oci23
Contact(s): Kullin Kour Dis

Caledon Club - Phase: 1B - Lot: 99B
16Oct23
Manjinder Singh Dhillon - Cell: (647) 309-5080 - (mdhillon475@gmail.com)
Kujit Kaur Dhillon - Cell: (647) 887-3200 - (dhillonk214@gmail.com)
Inderjit Singh - : (647) 987-3200 - (inderjitdhillon213@gmail.com)
mdhillon475@gmail.com

Email:

Company: Zancor-Caledon Attention: Telephone: Fax:

DAI	Type	Issue		Appt. Date/Time	3
164106	30-Day	Great Room- General- 1 INTERIOR Floor 01 Great/Grand/Family Room Wall chipped wall near the baseboard-trim	1	286	280ct23
164107	30-Day	Bedroom 2- General- 2 INTERIOR Floor 02 Bedroom Wall 3rd bedroom - baseboard has some yellow stuff but it has not been fixed completely - sand paint patch	7	N 75	280ct23 /am
164108	30-Day	Great Room- General- 3 INTERIOR Floor 01 Great/Grand/Family Room Other (Please describe) baseboard - it looks like a line in pic but is like a cut on the floor (see attached pic) ALSO, the same problem upstairs - gap	7	2 2 11	260ct23

164114	164112	164111	164110	164109	
30-Day	30-Day	30-Day	30-Day	30-Day	
Kitchen- General- INTERIOR Floor 01 Kitchen Cabinet(s) there is wood at the top of the cabinet needs to be covered up (very obvious)-NA UNDER-ISLAND - NO GABLE INSTALLED	Bedroom 2- General- 7 INTERIOR Floor 02 Bedroom Doors a couple of scratches on the door from before we moved in @trim	Great Room-General- 6 INTERIOR Floor 01 6 INTERIOR Floor 01 Great/Grand/Family Room Other (Please describe) Rogers is asking the builder to tell them which wire is the internet wire (to allow for connection everywhere in the house) right now they are using the neighbours internet wire temporarily - through the vent	Main Hall- General- 5 INTERIOR Floor 01 Hallway Wall the closet area between the garage and kitchen has not been fully painted	Bedroom 2- General- 4 INTERIOR Floor 02 Bedroom Doors a deep cut by the door in the master bedroom (it has a green tape on its side, but has not been fixed yet).	shoemold
260ct23	260ct23	26Oct23 /am	260ci23 /amp/23	260ct23 /am	
		Keblerco			

Data Completed	164115
total.	30-Day
21/26/20	Exterior- General- 10 EXTERIOR Not Applicable (Choose your next selection) Building Face/Exterior Windows the work on the windows not finished properly -PROVIDE PHOTO
Homeowner Signature:	26Oct23 /am
4112	

Date Completed: UCT

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

22

Signature

Print Name:

OCHER

Trade &/or Septice Tech.

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and It's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.