Enrollment:

Purchaser Name: ?????

Salwa Naim Amin Ghattas

Phone Res:

Phone Bus: (416) 858-8579

Closing Date: June 12, 2023
Inspector: Gisella Fiore

ZANCOR

Page 1 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 151 Unit 6 / 1

Plan: Address: Municiaplity:

Inspection Date: November 01, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

| EXTERIOR | | |
|----------------------|---|------|
| GARAGE DOORS | GARAGE DOORS NOT INSTALLED. | |
| NOTE: | AC NOT INSTALLED | |
| KITCHEN | | |
| CABINETS | CHIP ON RIGHT PANTRY DOOR BOTTOM RIGHT DOOR. | |
| | ADJUST RIGHT CABINET RIGHT OF HOODFAN LARGE GAP. | |
| | SHELF NOT INSTALLED INSIDE ISLAND. | |
| | CHIP ON UPPER LEFT CABINET LEFT OF HOODFAN | |
| | CHIP AT KICKPLATE RIGHT SIDE FLOOR LINE. | |
| SINK/FAUCET/PLUMBING | WATER LINE FOR FRIDGE NOT INSTALLED AS PER EXTRAS. | |
| NOTE: | ADJUST SLIDING DOOR VERY HARD TO OPEN AND CLOSE. | |
| WINDOWS | DAMAGED INTERIOR MULIN TRIMM RIGHT SIDE AT SLIDING DOOR | |
| FOYER/HALL | | |
| STAIRS | FILL NAIL HOLES ON TRIM AT STAIRS. | |
| | SECURE SCREW PLUG AT POST RIGHT OF TREAD BELOW NOSING AT LANDING TO 3RD FLOOR | |
| | STAIN AND VARNISH NOT COMPLETE BELOW NOSING AT TRIM AT LANDING TO 3RD FLOOR. | |
| | EXPOSED SCREW RIGHT SIDE BELOW NOSING AT 3RD FLOOR. | |
| | STAIN REQUIRED AT HARDWOOD PLANK BY NOSING AND LANDING TO 3RD FLOOR | |
| | CHIP ON 5TH TREAD AT STAIRS FROM MAIN TO 2ND FLOOR. | |
| MASTER BEDROOM | | |
| TRIM | SVC REPAIE TTRIM ABOVE FIXED DOOR AND ASTRICAL | |
| | TRIM SHORT RIGHT OF BALCONY DOOR | |
| | ADJUST SHIM TO BATH | |

Enrollment: Purchaser Name: ??????

Salwa Naim Amin Ghattas

Phone Res:

Phone Bus: (416) 858-8579 Closing Date: June 12, 2023 Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Purchaser's Signature HL

Lot / Phase: Block 151 Unit 6 / 1

Plan: Address: Municiaplity:

Inspection Date: November 01, 2023

| MAIN BATHROOM | | |
|-----------------|--|------|
| TRIM | CRACKED INTERIOR WINDOW JAMB | |
| VANITY CABINETS | POWDER-2ND FLOOR - CHIP AT BOTTOM GABLE BELOW SINK AND RIGHT SIDE GABLE. | |
| BEDROOM #2 | | |
| FLOORING | FLOOR SQUEAK IN BOTH BEDROOMS | |

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate.

?????? Salwa Naim Amin Ghattas Purchaser's Name (print)

Purchaser's Signature Purchaser's Name (print)

Gisella Fiore

Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature

Date (YYYY/MM/DD) 2023/11/01 November 01, 2023