Enrollment:

Purchaser Name: Joseph S HARNACK

Phone Res: (519) 570-6456

Phone Bus:

Closing Date: November 09, 2023

Inspector: Alexandria Damianidis

Page 1 of 2



Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 812 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 812

Municiaplity:

Inspection Date: November 03, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
CABINETS	CHIP AT BOTTOM GABLE AT UPPER CABINET LEFT OF MICROWAVE AND CHIP AT RIGHT	
	CABINET	
	ADJUST CABINETS ABOVE MICROWAVE - HITTING	
	CHIP AT UPPER CABINET ABOVE FRIDGE	
	CHIP AT CABINET BELOW SINK	
	DW NOT CONNECTED	
	CHIP AT CORNER COTTON CABINET AND ADJUST CABINET	
	SCRATCHES ON LOWER CABINET RIGHT OF STOVE AND SHELF NOT INSTALLED	
	CHIP AT FILLER PIECE LEFT OF MICROWAVE	
	CHIP AT FILLER PIECE AT CORNER AT BOTTOM CABINETS	
	SCRATCH AT UPPER CABINET LEFT OF MICROWAVE	
	CHIP AT CABINET BELOW SINK	
	PAINT/FILM ON FRIDGE GABLE -INSPECT AND REMOVE	
	HOMEOWNER UNHAPPY WITH GAP AT MOULDING ABOVE CABINETS, CAN THIS BE FILLED/CAULKED/PAINTED	
	CHIP ABOVE MICROWAVE AT FILLER PIECE -CAN SEE WHEN STANDING BACK	
WINDOWS	REPLACE SCREEN DOOR - DIRTY AND HAS PAINT	
FLOORING	HOMEOWNER UNHAPPY WITH GAP IN BETWEEN HARDWOOD PLANK BESIDE LEFT WALL- CAN	
	SEE SUB FLOOR BELOW	
MASTER BEDROOM		
WALLS	DOOR STOP NOT INSTALLED	
POWDER ROOM		
WALLS	HOMEOWNER UNHAPPY WITH GAPPING BETWEEN TILE AND DRYWALL AT SHOWER -FILL AND FIX	
FOYER/HALL		
NOTE:	REMOVE PAINT FROM LIGHT SWITCHES, OUTLETS, HINGES, AND DOOR HANDLES THROUGH	

Enrollment:

Purchaser Name: Joseph S HARNACK

Phone Res: (519) 570-6456

Phone Bus:

Closing Date: November 09, 2023 Inspector: Alexandria Damianidis

ZANCOR

Page 2 of 2

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 812 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 812

Municiaplity:

Inspection Date: November 03, 2023

LAUNDRY ROOM

WALLS

BIG HOLES IN DRYWALL BEHIND WASHING MACHINE

A REFERENCE FOR FUTURE WAR	RANTY REQUESTS. To designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHASI	
I have inspected my new home and	I agree that the description of the items listed	on this form are accurate.	
Joseph S HARNACK			
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Alexandria Damianidis	
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/11/03	November 03, 2023	