

ANCOR HOMES

Zancor Homes (Caledon) Ltd. Warranty Services

Work Order

Phone: (905) 738-7010 Fax: (905) 738-5948

Closing Date: 24Jul23

Address:

Location: Caledon Club - Phase: 1B - Lot: 5B 16Oct23

Today's Date:

Contact(s):

Tajinder Singh Saini - Cell: (647) 300-5449 - (tajindersaini@hotmail.ca) Kiranjot Kaur - Cell: (416) 884-7003 - (kiranjotjohal44@gmail.com) Vijay Saini - Cell: (437) 772-2398 - (vijaypalsaini1965@gmail.com)

Jaspal Kaur - Cell: (647) 522-4545 - (jaspalka1963@gmail.com)

Email: tajindersaini@hotmail.ca

Company: Zancor -Caledon

Attention:

Telephone:

Please Complete the following items:

162695	162690	162689	162681	DAI
30-Day	30-Day	30-Day	30-Day	Туре
Bedroom 2- General- Item #17 - BEDROOM 2 BASEBOARD HAS	Exterior- General- Item #12 - FILL GAPS ABOVE FRONT DOOR AT EXTERIOR BETWEEN SIDIND AND BRICK	Exterior- General- Item, #11 -DENTS ON FRONT DOOR ON TRIMS AND THROUGHOUT THE DOOR AND PAINT AND SCRATCHES ALL OVER	Other- General- Item #3 - Cracked air registers throughout the home. Very poor quality used	Issue
			25	
03Nov23 /am	03Nov23 /am	03Nov23 /am	03Nov23 /am	Appt. Date/Time
				Notes

162738	162733	162730	162728	162727	162724	162723	162722	
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Дау	
Exterior- General- Item #35 - House civic number in front of	Shared Bathroom- General- Item #30 - 2 washroom countertops silicone was done very irregular and messy. Needs to be redone	Bedroom 2 Ensuite-General- Item #28 - On suite secondary bedroom washroom behind the toilet has a big hole in the drywall around the plumbing	Shared Bathroom- General- Item #26 - Shared bathroom tiles missing grout and finishing.	Bedroom 2 Ensuite-General- Item #25 - Tub area in on suite washroom in secondary bedroom missing grout and finishing throughout the tub area tiles	Master Ensuite- General- Item #22 - Master Bedroom bathroom has drywall screws popping out of ceiling	Laundry Room- General- Item #21 - HVAC vent cover broken	Laundry Room- General- Item #20 - Very dirty scratched sink was left	VISIBLE WATER DAMAGE
75	7					75	75	
03Nov23 /am	03Nov23 /am	03Nov23 /am	03Nov23 /am	03Nov23 /am	03Nov23 /am	03Nov23 /am	03Nov23 /am	
			N.		ORRICE			

						, [
162753	162752	162751	162748	162744	162740	162739	
30-Day	30-Day	30-Дау	30-Дау	30-Day	30-Day	30-Day	0.7.7
Master Bedroom-	Kitchen- General- Item #49 - Kitchen floor close to the patio door needs cleaning. Big mark of paint roller dropped.	Kitchen- General- Item #48 - REQUESTING BACK SPLASH TILE TO BE USED BEHIND STOVE INSTEAD OF GROUT Filled instead of a full piece of tile insert. Very irregular finish of back splash by the kitchen exhaust fan	Bedroom 2- General- Item #45 - Door stopper missing in bedroom 2 Door leasing to shared on suite	Shared Bathroom- General- Item #40 - ADJUST DOOR TO SHARED BATH CANNOT CLOSE	Kitchen- General- Item #37 - Dap around the countertop missing or irregular in kitchen at various spots and the back splash trim or edging needs to be cleaned	Powder Room- General- Item #36 - ADJUST WEATHER STRIP AT WINDOW. At powder room	house still missing. As per site its back ordered
$\overline{\ }$	= = = = = = = = = = = = = = = = = = = =		3/	77	75		
03Nov23	03Nov23 √am	03Nov23 /am	0aNov23 /am	03Nov23 Jam	03Nov23 /am	03Nov23 /am	
						KEDIREET 70 NOWMAR	

162765	162764	162761	162760	162759	162755	162754	
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	
Exterior- General- Item #59 - Side enterance to the basment. The	Bedroom 3 Ensuite- General- Item #58 - Bedroom 3 washroom has scratches on the tub on the outside	Master Ensuite- General- Item #55 - Rough drywall and paint finish in toilet area at masterbedroom wasroom.	Master Bedroom- General- Item #54 - Master bedroom door close very tight and has a damaged trim	Bedroom 3- General- item #53 - Bedroom 3 next to master walkin closet Has a damaged basebord installed. Requires replacement.	Shared Bathroom-General- Item #52 - Shared bathroom door leading to toilet and shower area. The lock does not click in the notch.	Other- General- Item #51 - Heat register covers throughout the home are cracked needs to be checked / and replaced.	General- Item #50 - Heat register in master bedroom below the window needs cleaning. Paint spilled in it
	2/2		75		75	2/5	· Kg
03Nov23 /am	03Nov23 /am	03Nov23 /am	03Nov23 /am	03Nov23 /am	03Nov23 /am	03Nov23 Jam	/am

door placement is in the wrong direction.	
Date Completed:	Homeowner Signature: Tayuda Sa
	The Homeowner acknowledges and accepts all work has been completed in a workman like manner.
Date Completed: 123	Trade &/or Service Tech.
	Signature:
	Print Name: Same

appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be

Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: 41B

190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	<u>26Sep23</u>	29May23	<u>Date</u> Reported
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	Interval	PDI	Type
13	12	11	10	9	00	7	6	S	4	υ.	2	P	2	16	Number
Exterior- General- Light not fixed properly-SECURE	Bedroom 2- General- Bedroom 2 Multiple touch up spots missed. Mentioned in PD	Master Bedroom- General- Master Bedroom Multiple touch up spots missed. Mentioned in PD	Living Room- General- Multiple touch up spots missed. Mentioned in PD	Bedroom 3 Ensuite- General- Shower wall mount fixture not flush in Bedroom 3 Ensuite. Also check main washroom fixtur	Main Bathroom- General- Shower rod not provided in Main washroom	Main Bathroom- General- Main bathroom - Caulking at sink not completed. Mentioned in PDI	Main Bathroom- General- Shower wall mount fixture not flush in Main Bathroom	Master Bedroom- General- Master bedroom spots needed repaint or missed on doors and walls. Mentioned in PDI and market with painters tape but not completed.	Master Bedroom- General- Master bedroom showing yellow lines at joining of ceiling and wall at 2 places - possible leakage, plus paint touch up at various spots on walls and doors including walk in closets	Master Ensuite- General- Master Bedroom Ensuite Ventilation fan noisy and not installed properly	Master Ensuite- General- Master Bedroom Ensuite floor AC Vent not fixed properly. Broken piece left in. Remove and Replace	Kitchen- General- chip - 5th tile from Patio door. Mentioned in PDI	Throughout- General- doors needs to be adjusted	Exterior- General- PORCH~CHIPS AT FRONT PORCH AND TREAD	Deficiency Description
Dart Electric 165382	Zancor - Caledon 165381	Zancor - Caledon 165380	Zancor - Caledon 165379	Zancor - Caledon 165378	Icon Plumbing & Heating 165377	Zancor - Caledon 165376	Zancor - Caledon 165375	Zancor - Caledon 165374	Zancor - Caledon 165373	Dart Electric 165372	Zancor - Caledon 165371	AV Classic 165370	<u>VIA Trim</u> <u>and Doors</u> <u>Inc.</u> 163351	Toronto Concrete & Drain 157367	Trade Assigned
Add	Add	Add	Add	Add	Add	<u>Add</u>	<u>Add</u>	Add	Add	Add	Add	Add	Add	Add	Add Trade
03Nov23	<u>03Nov23</u>	03Nov23	<u>03Nov23</u>	<u>03Nov23</u>	03Nov23	<u>03Nov23</u>	03Nov23	<u>03Nov23</u>	<u>03Nov23</u>	03Nov23	03Nov23	03Nov23	<u>03Nov23</u>	03Nov23	Appointment Date
	7	, \	\	5			1	7			1				Item Completed
	F	7		1		K	7	F	2		=				Initial

190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	190ct23	19Oct23
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day
32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14
Bedroom 3- General- bedroom 3 wall and closet + doors touch up.	Bedroom 4- General- bedroom 4 touch up on walls and door	Bedroom 3- General- Bedroom 3 ensuite shower takes a few minutes to warm up. way longer than other showers-INSPECT	Foyer- General- paint touch up needed on walls near basement and side entranc	Powder Room- General- powder room door, frame and wall paint touch ups	Foyer- General- mudroom-paint touch ups	Bedroom 3 Ensuite- General- bedroom 3 ensuite water pressure very poor	Foyer- General- nail mentioned in PDi removed but pain not matching the steps. touch up of stair correct paint needed.	Foyer- General- Staircase wall multiple touchups - mentioned on PDI - not complete	Foyer- General- front door and entrance closet door adjustment as mentioned in PD	Foyer- General- linen closet door chips	Kitchen- General- multiple chips on cabinets as mentioned in PDI lis	Bedroom 2- General- Bedroom 2 closet Yellow line marks again at wall joint - paint touch up needed	Foyer- General- hips on most closet and bedroom doors - need touch u	Exterior- General- Front door outer multiple chips - paint coat needed	Stairs- General- chip on steps mentioned in PD	Kitchen- General- Multiple chips mentioned at PDI not rectified	Exterior- General- Steps wobbly at entrance. Affix firmly.	Exterior- General- multiple gaps in brick on exterior back waLL-PHOTO
Zancor - Caledon 165401	Zancor - Caledon 165400	Icon Plumbing & Heating 165399	Zancor - Caledon 165398	Zancor - Caledon 165397	Zancor - Caledon 165396	Icon Plumbing & Heating 165395	Perfect Touch - CALEDON 165394	Zancor - Caledon 165393	<u>Newmar</u> 165392	Zancor - Caledon 165391	New Image Kitchens 165390	Zancor - Caledon 165389	Zancor - Caledon 165388	Perfect Touch - CALEDON 165387	Zancor - Caledon 165386	New Image Kitchens 165385	Zancor - Caledon 165384	Zancor - Caledon 165383
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add
03Nov23	03Nov23	03Nov23	<u>03Nov23</u>	03Nov23	03Nov23	03Nov23	03Nov23	<u>03Nov23</u>	03Nov23	03Nov23	<u>03Nov23</u>	03Nov23	03Nov23	03Nov23	03Nov23	03Nov23	<u>03Nov23</u>	03Nov23
			1	1	1		1	1		1			1	/	CONCRE		FNO XCHII	
2	K		K	M	N. A. C.		K	7		F			8	7	70 7		7	

190ct23
30-Day
ယ္သ
Bedroom 3- General- bedroom 3 ensuite paint touch ups
Zancor - Caledon 165402
Add
03Nov23
/
7

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: Moy Sancor Service Technician: Koes