

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2 TEL (905) 672-1233 FAX (905) 672-1076 WO # W19017 Pack Slip:5521

Service Date: Sep 25, 2023

HI-KISE			, ,			• ′	
Priority:	Normal		Status:	SCHEDULED			COMMENSATION OF THE PARTY OF TH
BUILDER	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~			OOHLBOLLD		***************************************	***************
Customer:	8030030		City:	OAKVILLE	Possiva	d. 0- 0-	
Name:	ZANCOR THE BRANCH CO	NDOS	Service Phone(s):	OARVILLE	Receive Time :	ed: Sep 05,	2023
Service Fax:	· ·		Site Phone:	(416) 566-2066		1100446	
Site Fax:			Lot#:	2ND FLOOR	Phase:	H80116	3-1
RESIDENT	INFORMATION			ZNDTEOON	rnase.	210	
Home Owner	Name:	***************************************	Address:	***			**************************************
Home Phone(s):		Work Pho	ine(s).				
Cell Phone(s):		Email(s):	(3).				
LINKED OR	DER INFORMATION (H801	163-1)		***************************************	***************************************	**************************************	************************
	8030030 ZANCOR THE BRAN		**************************************	House Model:	2ND ELOOP	******************	nakanangan sa
	2ND FLOOR	Phase:		Elevation:	ZND FLOOR		
SERVICE IN	STRUCTIONS		and the state of t	Lievation.	dan and an angle an		Acres - 5 - 55 - 111 - 115 - 115 - 115 - 115 - 115 - 115 - 115 - 115 - 115 - 115 - 115 - 115 - 115 - 115 - 115
INVESTIGATE	E AND CORRECT	**************************************			~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		d-000000000000000000000000000000000000
	M SLIDING DOOR ACTS AS (GUARDRAIL.	OPERABLE DOOR	PANEL REQUIR	RES OPENING RE	STRICTOR~	Ocus
	PT 5TH 2023***CLOSING ON						
							.P%
SCREEN DO	PDI - MASTER BEDROOM W OR	'INDOWS- W	INDOW SCREENS A	AND CRACKS TH	HROUGHOUT NO	T INSTALLED	Sol
PARTS REQ	UIRED						
LN Item Descri	ption	Location	Specification	Size	Options		helista kalik kanaya ya pak dana.
	SED PATIO DOOR	WBCH2-ES		70 3/16 X 88	MEDIUM GRAY	/ LICEV11020	Qty
NEED WEED WEED FRAME	HITE BUMPER ON CENTER	6	REPLACEMENT PARTS	1/16	BONE WHITE U		1
		71			, , , , , , , , , , , , , , , , , , ,		
Problem Descri	ption:	YLLJE					***************************************
Warranty			CHARG	EABLES			•••••••••••••••••••••••••••••••••••••••
1aterial \$			Material \$				
abour\$	***************************************		Labour \$				
			P.O.#:				
ause:							

olution:		99929999999999999999999999999999999999					

		······································					······································
Date Complet	ed: <u>Sept-25</u>	2073	Approv	ed:			
Tir	me:		Service Signatu	ire: To	40-5 JORGE	Van	- Control of the Cont
				χ /	,		