

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2 TEL (905) 672-1233 FAX (905) 672-1076 WO # W19546 Pack Slip:5567

Service Date: Oct 02, 2023

ACTURE VENEZUA EN ERRORERO DE CONTROLO DE						
Priority:	Normal	,	Status:	SCHEDULED		
BUILDER						
Customer:	8030030		City:	OAKVILLE	Received:	Sep 26, 2023
Name:	ZANCOR THE BRANC	CH CONDOS	Service Phone(s):		Time:	
Service Fax:			Site Phone:	(416) 566-2066	Order:	H801164-1
Site Fax:			Lot#:	3RD FLOOR	Phase:	305
RESIDENT	INFORMATION					
Home Owner Name:			Address:			
Home Phone(s):			Work Phone(s):			
Cell Phone(s):			Email(s):			
LINKED OF	RDER INFORMATION	I (H801164-1)				
Customer:	8030030 ZANCOR THE	BRANCH CONDO	S	House Model: 3RD	FLOOR	
Lot #:	3RD FLOOR	Phase:		Elevation:		
SERVICE IN	ISTRUCTIONS					
CLOSING	ON OCTOBER 23RD 20	023				
INIVECTIOAT	E AND CORRECT			~ ~ ~ P.		
INVESTIGAT	E AND CORRECT			DONE		
DAI #163421	- PDI - BEDROOM 2 W	INDOWS - WINDOV	V TRIM, RIGHT ANI	D LEFT SIDE OF OPE	RATE A WINDO\	V CUT SHORT
· DAL#462422	- PDI - LIVING ROOM \	ANNIDONAIS DAMAG	SEMULUM DICHT	OF ODEDATING WIN	DOW ~	
DAI#103422	- FDI - LIVING ROOW V	WINDOWS - DAWAC	3L MOLLIN, MGITI			
Problem Desc	cription. NAT	NEWHAR	DRYWA	U RETURN	/	
					999	
Warranty			CHARGEABLES			
Material \$		Material \$				
Labour \$		Labour \$	<u> </u>			
			P.O.#:			
Cause:						
0.1.0				· · · · · · · · · · · · · · · · · · ·		
Solution:						
·····						

Date Completed:			Approved:			
	HARLES A. A.					-
	Time:		Service Sian	ature:		
					KHEM	