



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W196602

Pack Slip:231393

Service Date: Nov 17, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 611313 City: INNISFIL Received: Sep 08, 2023
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time: PM
Service Fax: Site Phone: Order: D389094-1
Site Fax: Lot#: 327W Phase: 3

RESIDENT INFORMATION

Home Owner Name: MICHAEL IGHADALO ITAMAN Address: BELLE AIRE SHORES - PHASE: 3 - LOT: 327W
Home Phone(s): Work Phone(s):
Cell Phone(s): 416-356-5948, 416-356-9841 Email(s): itamanmichael@yahoo.com, agenelizzy15@gmail.com

LINKED ORDER INFORMATION (D389094-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 327W
Model: 42-06 MASTHEAD/OP 2FL/DW Phase: 3

SERVICE INSTRUCTIONS

EXTERIOR- NOTE:-INSPECT WINDOWS OUT FRONT PORCH MISSING PLUGS.

BEDROOM 2 ENSUITE- NOTE:-SECURE WINDOW CRANK LIGHT COMING THROUGH.

BEDROOM #2- WINDOWS-RIPPED SCREEN.

ADD:

KITCHEN- GENERAL- LIGHT THROUGH WINDOW CRANK HANDLE ON KITCHEN, FAMILY ROOM, BEDROOM 3, BEDROOM 4 ENSUITE, MASTER BEDROOM ENSUITE WINDOWS.- SVC SECURE

ADD ON 10/30/23

165997 FOYER- GENERAL- AIR

LEAKAGE AROUND EXTERIOR DOORS WAS APPARENT AT THE TIME OF THE INSPECTION - FRONT DOOR

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
72	NEWMAR VINYL CASEMENT	B2	SCREENS-REPLA CEMENT-WINDO WS	25.0625 X 35.125		1
213	620C_STYLE DOORLITE CUSTOM screw caps /strips	FOY	OTHER RPLCMNT PARTS	22 X 36	620C_STYLE DOORLITE CUSTOM	1

Problem Description:

H/O Sign Breakage w/o
No Backups provided

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$

Labour \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed: Nov 17 / 23

Approved: Michael Stana

HOME OWNER'S NAME W SIGNATURE

Time: 45 min

Service Signature: [Signature]
STEVE